

Fire Safety Inspection Report

Fire Safety Inspection Report

Building Name: GOKULDAM SOCIETY

Inspection Date: 2024-10-04

Inspector Name: CHALU PANDEY

1. Inspection Summary:

This inspection of GOKULDAM SOCIETY was conducted on 2024-10-04. The inspection revealed

- Fire extinguishers: Not present on the ground floor and expired on the second floor.
- Fire alarm: Functional and working correctly.
- Exits: Overall condition rated as 5 (presumably on a scale of 1-5, with 5 being the best).

2. Detailed Findings:

Fire Extinguishers:

- Ground Floor: No fire extinguishers were found on the ground floor.
- Second Floor: One fire extinguisher was found on the second floor, but it was expired.

Fire Alarm System:

- Functionality: The fire alarm system was tested and found to be functional.
- Maintenance: No information was provided regarding the last maintenance check of the system.

Exits:

- Condition: The overall condition of the exits was rated as 5, indicating they are in good condition.

3. Risk Assessment:

- High Risk: The absence of fire extinguishers on the ground floor and the presence of an expired
- Moderate Risk: While the fire alarm system is functional, the lack of information regarding its ma
- Low Risk: The good condition of the exits mitigates the risk of evacuation difficulties in the even