

# Fire Safety Inspection Report

## Fire Safety Inspection Report

Building Name: GOKULDAM SOCIETY

Inspection Date: 2024-10-04

Inspector Name: CHALU PANDEY

### 1. Inspection Summary:

This inspection revealed significant deficiencies in fire safety equipment at GOKULDAM SOCIETY.

### 2. Detailed Findings:

- Fire Extinguishers:
  - Ground Floor: No fire extinguishers were found.
  - Second Floor: Expired fire extinguishers were found.
- Fire Alarm: Functional and in working order.
- Exits: All exits were accessible and in good condition (rated 5/5).

### 3. Risk Assessment:

The lack of fire extinguishers on the ground floor presents a significant risk to occupants in case of a fire.

- Delayed response: Occupants may not be able to contain a fire in its early stages without fire extinguishers.
- Increased risk of injury: Without proper fire suppression, a fire can spread rapidly, increasing the risk of injury to occupants.
- Increased property damage: A fire that is not quickly contained can cause significant damage to the building and its contents.

### 4. Next Steps:

#### 1. Immediate Action:

- Install fire extinguishers on the ground floor: The building management should immediately purchase and install fire extinguishers on the ground floor.
- Replace expired fire extinguishers: The expired fire extinguishers on the second floor should be replaced with new ones.
- Ensure fire extinguisher maintenance: A regular maintenance schedule for all fire extinguishers should be established.

#### 2. Long-term Action:

- Develop a comprehensive fire safety plan: The building management should develop a comprehensive fire safety plan, including evacuation procedures and fire drills.
- Conduct regular fire drills: Regular fire drills should be conducted to ensure occupants are familiar with evacuation procedures.
- Train staff and residents on fire safety: Staff and residents should be trained on the proper use of fire extinguishers and other fire safety equipment.