

Fire Safety Inspection Report

Fire Safety Inspection Report

Building Name: GOKULDAM SOCIETY

Inspection Date: 2024-09-09

Inspector Name: CHALU PANDEY

1. Inspection Summary

This inspection revealed significant fire safety deficiencies within GOKULDAM SOCIETY. The ab

2. Detailed Findings

- Fire Extinguishers:
 - Presence: No fire extinguishers were found on the premises.
 - Condition: N/A (Not Applicable)
 - Comments: The inspection report states that fire extinguishers were previously present but h
- Fire Alarm System:
 - Condition: Non-Functional
 - Comments: While a fire alarm system is present, it was found to be non-functional. This mea
- Exits:
 - Number: 3
 - Condition: No information provided on the condition of the exits. Further inspection is require

3. Risk Assessment

The lack of fire extinguishers and a non-functional fire alarm system significantly increases the ris

- Delayed evacuation: Without a functioning fire alarm, occupants may not be alerted to a fire in t
- Inability to contain fire: The lack of fire extinguishers hinders the ability to contain a fire in its ear
- Increased risk of injury or fatality: The combination of these deficiencies significantly increases t

4. Next Steps

Immediate Action:

- Install fire extinguishers: The building management should immediately purchase and install ap