

UFB Connect - MDU / ROW Checklist - 5

conducted for

Fabril Solutions Ltd

Customer address

6A burnsall Place, Avondale

Field Manager

Neil panther

CSA

07

iTools Reference number -

133226

Conducted on

23/02/2561 BE, 9:35 AM

Prepared by

Kranthi Kumar Thota














Score







15/27 - 55.56%

Audit - 10/20 - 50%

Question	Response	Details
Site Type	ROW - Right of Way	
Class key	Class 1 - MDU/ROW 2-5	
Fibre Installation Checklist - Communal Area	Hard, Soft, Surface Mount, Jointing	
Excavation type	Trench - linear meters	
How many meters?	6.5 metres	
Hard surface type	Concrete	
Excavation type	Concrete Slot Cut - Linear Meters	
How many meters?	7.4 metres	
Hardware Installation Checklist		
Quantity of Hardware installed? e.g 1x RAT, 2x 30m Ruggedize	1 50mm to 25mm reducer 3 metres conduit	
Was the equipment installed, laid up and labelled correctly?	Yes	
Has CVLS testing been completed?	N/A ABF	

As-built photo evidence - 5/7 - 71.43%

Question	Response	Details
Photo of MDU/ROW starting point as per design document	Yes	
2) Photos of MDU/ROW starting point as per scoping document.		
 <p>Appendix 1</p>  <p>Appendix 2</p>		
Additional information of MDU/ROW starting point as per scoping document		
Photo of surfaces prior to works e.g trenching / slot cutting	Yes	
Photo of surfaces prior to works e.g trenching / slot cutting		
 <p>Appendix 3</p>  <p>Appendix 4</p>  <p>Appendix 5</p>  <p>Appendix 6</p>  <p>Appendix 7</p>  <p>Appendix 8</p>		
Additional information of surfaces prior to works e.g trenching / slot cutting		
Photos where change in methodology occurs e.g. shallow trench to surface mount	Yes	
Photos where change in methodology occurs e.g. shallow trench to surface mount		
 <p>Appendix 9</p>  <p>Appendix 10</p>  <p>Appendix 11</p>  <p>Appendix 12</p>  <p>Appendix 13</p>		
Additional information where change in methodology occurs e.g. shallow trench to surface mount		

Question	Response	Details
Photos where change in surface type occurs		
Photos where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs	Yes	
Photos where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs		
<div><p>Appendix 14</p></div>	<div><p>Appendix 15</p></div>	
Additional information where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs		
Photos of surfaces after final permanent reinstatement	Yes	
Photos of surfaces after final permanent reinstatement		
<div><p>Appendix 16</p></div>	<div><p>Appendix 17</p></div>	<div><div><div><p>Appendix 18</p></div></div><div><p>Appendix 19</p></div></div>
Additional information - e.g dimensions of concrete cut, removed and reinstated.		
Is site ready for provisioning?		


Media



Appendix 1




Appendix 2




Appendix 3



Appendix 4



Appendix 5



Appendix 6



Appendix 7



Appendix 8



Appendix 9



Appendix 10



Appendix 11



Appendix 12



Appendix 13




Appendix 14




Appendix 15




Appendix 16



Appendix 17



Appendix 18



Appendix 19