

UFB Connect - MDU / ROW Checklist - 5

conducted for

Fabril Solutions Ltd

Customer address

8 Latham avenue

Field Manager

Regan Foai

CSA

07

iTools Reference number -

138741

Conducted on

15 May 2018 10:45 PM

Prepared by

Kranthi Kumar Thota







Score








16/27.0 - 59.26%

Audit - 10/20 50.00%

Question	Response	Details
Site Type	ROW - Right of Way	
Class key	Class 1 - MDU/ROW 2-5	
Fibre Installation Checklist - Communal Area	Hard, Soft, Surface Mount	
Excavation type	Trench - linear meters	
How many meters?	28 metres	
Hard surface type	Concrete	
Excavation type	Concrete Slot Cut - Linear Meters	
How many meters?	4 metres	
Hardware Installation Checklist	Other	
Quantity of Hardware installed? e.g 1x RAT, 2x 30m Ruggedize	NA	
Was the equipment installed, laid up and labelled correctly?	Yes	
Has CVLS testing been completed?	N/A ABF	

As-built photo evidence - 6/7 85.71%

Question	Response	Details
Photo of MDU/ROW starting point as per design document	Yes	
2) Photos of MDU/ROW starting point as per scoping document.		
<div style="display: flex; justify-content: space-around; align-items: flex-end;"> <div style="text-align: center;">  <p>Appendix 1</p> </div> <div style="text-align: center;">  <p>Appendix 2</p> </div> </div>		
Additional information of MDU/ROW starting point as per scoping document		
Photo of surfaces prior to works e.g trenching / slot cutting	Yes	
Photo of surfaces prior to works e.g trenching / slot cutting		
<div style="display: flex; justify-content: space-around; align-items: flex-end;"> <div style="text-align: center;">  <p>Appendix 3</p> </div> <div style="text-align: center;">  <p>Appendix 4</p> </div> <div style="text-align: center;">  <p>Appendix 5</p> </div> <div style="text-align: center;">  <p>Appendix 6</p> </div> </div>		
Additional information of surfaces prior to works e.g trenching / slot cutting	Clip conduit on wall for 14.5 metres	
Photos where change in methodology occurs e.g. shallow trench to surface mount	No - N/A	
Why no photo's where methodology changes?	No changes in methodology	
Photos where change in surface type occurs	Yes	

Question	Response	Details
<p>Photos where change in surface type occurs</p> <div>   </div> <p>Appendix 7 Appendix 8</p>		
Additional information where change in surface type occurs		
Photos where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs		Yes
<p>Photos where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs</p> <div>   </div> <p>Appendix 9 Appendix 10</p>		
Additional information where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs		
Photos of surfaces after final permanent reinstatement		Yes
<p>Photos of surfaces after final permanent reinstatement</p> <div>    </div> <p>Appendix 11 Appendix 12 Appendix 13</p>		
Additional information - e.g dimensions of concrete cut, removed and reinstated.		NA
Is site ready for provisioning?		Yes

Media



Appendix 1



Appendix 2



Appendix 3



Appendix 4



Appendix 5



Appendix 6



Appendix 7



Appendix 8



Appendix 9



Appendix 10



Appendix 11



Appendix 12



Appendix 13