

UFB Connect - MDU / ROW Checklist - 5

conducted for

Fabril Solutions Ltd

Customer address

180b Barrack Road

Field Manager

Neil panther

CSA

07

iTools Reference number -

136569

Conducted on

18 Apr 2018 03:55 AM

Prepared by

Kranthi Kumar Thota

Completed on

22 Apr 2018 09:55 PM










Score







15/27.0 - 55.56%







Audit - 9/20 45.00%

Question	Response	Details
Site Type	ROW - Right of Way	
Class key	Class 1 - MDU/ROW 2-5	
Fibre Installation Checklist - Communal Area	Hard, Soft	
Excavation type	Trench - linear meters	
How many meters?	81 metres	
Hard surface type	Concrete	
Excavation type	Concrete Slot Cut - Linear Meters	
How many meters?	14.1 metres	
Hardware Installation Checklist	Other	
Quantity of Hardware installed? e.g 1x RAT, 2x 30m Ruggedize	1*8m conduit	
Was the equipment installed, laid up and labelled correctly?	Yes	
Has CVLS testing been completed?	N/A ABF	

As-built photo evidence - 6/7 85.71%

Question	Response	Details
Photo of MDU/ROW starting point as per design document	Yes	
2) Photos of MDU/ROW starting point as per scoping document.		
 <p>Appendix 1</p>		
Additional information of MDU/ROW starting point as per scoping document		
Photo of surfaces prior to works e.g trenching / slot cutting	Yes	
Photo of surfaces prior to works e.g trenching / slot cutting		
 <p>Appendix 2</p>  <p>Appendix 3</p>  <p>Appendix 4</p>  <p>Appendix 5</p>  <p>Appendix 6</p>  <p>Appendix 7</p>  <p>Appendix 8</p>  <p>Appendix 9</p>		
Additional information of surfaces prior to works e.g trenching / slot cutting		
Photos where change in methodology occurs e.g. shallow trench to surface mount	No - N/A	
Why no photo's where methodology changes?	There is no changes in methodology	

Question	Response	Details
Photos where change in surface type occurs	Yes	
<p>Photos where change in surface type occurs</p> <div>    </div> <div> <p>Appendix 10</p> <p>Appendix 11</p> <p>Appendix 12</p> </div>		
Additional information where change in surface type occurs		
Photos where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs	Yes	
<p>Photos where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs</p> <div>    </div> <div> <p>Appendix 13</p> <p>Appendix 14</p> <p>Appendix 15</p> </div>		
Additional information where assets installed e.g. hand holes, IFDB's, Pedestals, BUD's, boundary pegs		
Photos of surfaces after final permanent reinstatment	Yes	

Question	Response	Details			
Photos of surfaces after final permanent reinstatment					
					
Appendix 16	Appendix 17	Appendix 18	Appendix 19	Appendix 20	Appendix 21
Additional information - e.g dimensions of concrete cut, removed and reisntated.		NA			
Is site ready for provisioning?		Yes			

Media



Appendix 1



Appendix 2



Appendix 3



Appendix 4



Appendix 5




Appendix 6



Appendix 7



Appendix 8



Appendix 9



Appendix 10



Appendix 11



Appendix 12



Appendix 13



Appendix 14



Appendix 15



Appendix 16



Appendix 17



Appendix 18



Appendix 19



Appendix 20



Appendix 21