


Required Materials - Can be bought from ULINE.com

- 1/4in foam 12x12in perforated roll
- 1/4in foam 12x6in perforated roll
- small bubble 12x24in perforated roll
- 2in removable low adhesive masking or painters tape




Fold 1 piece of 12x12x1/4in foam 2 times and stick between scanner and scanner hood.

Tape the hood, around the folded foam under the scanner compartment, to the bottom of the BMD.

2 layers of 12x6x1/4in foam (2 piece length, 24in total length), tucked between BMD and container foam. The end is wrapped around the foam corner, padding the scanner hood.

Additional layer of 12x6x1/4in foam behind scanner hood. (Some units need 2 or 3 pieces).

1 piece of 12x12x1/4in foam taped over scanner hood.



Cut a 12x6x1/4in piece down to 12x1x1/4in piece and place between scanner hood and foam on this side. (Some units may require 2 pieces).

Tape over controller

1 piece of bubble wrap over screen, taped on top and bottom.

1" thick strip of foam between screen and scanner lid.

2 pieces of 12x6x1/4in foam folded and taped.