

Date	Revision	Description

[illegible]

Erratum Number	Erratum Title	Revision(s) Affected

1 JTAG

1.1 JTAG INTEST instruction does not work

Description:

Workaround:

Silicon Revision Affected:

Fixed:

1.2 The Recover Locked Device sequence does not work as expected

Description:

Workaround:

1.

2.

3.

4.

Silicon Revision Affected:

Fixed:

2 System Control

2.1 Sleep and Deep-Sleep mode not usable at higher speeds when ISRs reside in Flash memory

Description:

Workaround:

1.

2.

Silicon Revision Affected:

Fixed:

2.2 Device Capabilities registers may not accurately reflect available signals

Description:

DC3

DC4

DC5

DC8

Workaround:

Silicon Revision Affected:

Fixed:

2.3 The PIOSC is not trimmed by the factory

Description:

Workaround:

Silicon Revision Affected:

Fixed:

3 Internal Memory

3.1 Cumulative page erases may introduce bit errors in Flash memory

Description:

Workaround:

1.

2.

Silicon Revision Affected:

Fixed:

3.2 Flash Write Buffer does not function above 50 MHz

Description:

Workaround:

Silicon Revision Affected:

Fixed:

4 ROM

4.1 Ethernet fails to connect when using the Boot Loader software in ROM

Description:

Workaround:

Silicon Revision Affected:

Fixed:

4.2 Some ROM functions are unsupported

Description:

Workaround:

Silicon Revision Affected:

Fixed:

4.3 ROM mapping check for the Boot loader does not function properly

Description:

Workaround:

Silicon Revision Affected:

Fixed:

4.4 ROM_I2CMasterErr function is incorrect

Description:

I2CMCS

Workaround:

Silicon Revision Affected:

Fixed:

4.5 ROM_SSICfgSetExpClk function is incorrect

Description:

Workaround:

Silicon Revision Affected:

Fixed:

4.6 ROM_USBFIFOFlush function is incorrect

Description:

Workaround:

Silicon Revision Affected:

Fixed:

4.7 The option to force the ROM boot loader to execute at reset with an external pin does not function

Description:

PORT	PIN	Boot Configuration (BOOTCFG)
------	-----	------------------------------

Workaround:

Silicon Revision Affected:

Fixed:

5 μ DMA

5.1 The μ DMA controller fails to generate capture mode DMA requests from Timer A in the Timer modules

Description:

Workaround:

Silicon Revision Affected:

Fixed:

6 GPIO

6.1 Port B [1:0] pins require external pull-up resistors

Description:

Workaround:

Silicon Revision Affected:

Fixed:

6.2 Schmitt input feature does not function correctly

Description:

Workaround:

Silicon Revision Affected:

Fixed:

7 EPI

7.1 EPI dual-chip select function does not work

Description:

CSCFG

CSCFG
EPI Host-Bus 8 Configuration 2 (EPIHB8CFG2)

CSCFG

CSCFG

Workaround:

Silicon Revision Affected:

Fixed:

7.2 EPI Host-Bus 16 mode does not work

Description:

MODE

EPI Configuration (EPICFG)

Workaround:


Silicon Revision Affected:

Fixed:

7.3 Clock signal in EPI General-Purpose mode is inverted

Description:

Figure 1. Timing Differences Between Rev B and Rev C Devices



Workaround:

Silicon Revision Affected:

Fixed:

8 General-Purpose Timer

8.1 The General-Purpose Timer match register does not function correctly in 32-bit mode

Description:

GPTM Timer A Match (GPTMTAMATCHR)

Workaround:

Silicon Revision Affected:

Fixed:

8.2 A spurious DMA request is generated when the timer rolls over in Input-Edge Time mode

Description:

Workaround:

Silicon Revision Affected:

Fixed:

8.3 A spurious DMA request is generated when the timer rolls over the 16-bit boundary

Description:

Workaround:

Silicon Revision Affected:

Fixed:

8.4 The value of the prescaler register is not readable in Edge-Count mode

Description:

GPTM Timer n (GPTMTnR)
GPTM Timer n Prescale (GPTMTnPR)

Workaround:

Silicon Revision Affected:

Fixed:

8.5 ADC trigger and Wait-on-Trigger may assert when the timer is disabled

Description:

GPTM Timer n Match (GPTMTnMATCHR)
TnOTE GPTM Control (GPTMCTL)
TnWOT TnEN GPTMCTL
GPTMTnMATCHR
GPTM Timer n Mode (GPTMTnMR)

Workaround:

TnOTE

Silicon Revision Affected:

Fixed:

8.6 Wait-on-Trigger does not assert unless the TnOTE bit is set

Description:

TnOTE GPTMCTL

Workaround:

TnWOT GPTM Timer n Mode (GPTMTnMR)
TnOTE GPTMCTL
TnOTE

Silicon Revision Affected:

Fixed:

8.7 Do not enable match and timeout interrupts in 16-bit PWM mode

Description:

Workaround:

GPTMTnMR GPTMIMR

Silicon Revision Affected:

Fixed:

8.8 Do not use μ DMA with 16-bit PWM mode

Description:

Workaround:

Silicon Revision Affected:

Fixed:

8.9 Writing the GPTMTnV register does not change the timer value when counting up

Description:

GPTM Timer n Value (GPTMTnV)

Workaround:

Silicon Revision Affected:

Fixed:

8.10 The prescaler does not work correctly when counting up in periodic or one-shot mode

Description:

Workaround:

Silicon Revision Affected:

Fixed:

8.11 Snapshot must be enabled in both Timer A and B when in 32-bit snapshot mode

Description:

GPTM Timer A (GPTMTAR)

Workaround:

TASNAPS

TBSNAPS

GPTM Timer A Mode (GPTMTAMR)
GPTMTAR

Silicon Revision Affected:

Fixed:

9 Watchdog Timer 1

9.1 Writes to Watchdog Timer 1 module WDTLOAD register sometimes fail

Description:

Load (WDTLOAD)

WRC

Watchdog
WDTCTL1

Workaround:

WDTLOAD

Silicon Revision Affected:

Fixed:

10 ADC

10.1 ADC hardware averaging produces erroneous results in differential mode

Description:

Workaround:

Silicon Revision Affected:

Fixed:

10.2 The ADCSPC register does not function

Description:

ADC Sample Phase Control (ADCSPC)

Workaround:

Silicon Revision Affected:

Fixed:

11 UART

11.1 UART Smart Card (ISO 7816) mode does not function

Description:

UnTX

Workaround:

Silicon Revision Affected:

Fixed:

11.2 When in IrDA mode, the UnRx signal requires configuration even if not used

Description:

UnRx

Workaround:

UnRx

UnRx

UnRx

Silicon Revision Affected:

Fixed:

11.3 Phantom interrupts occur in Smart Card mode

Description:

UARTRIS

UARTMIS

Workaround:

PEMIS

PERIS

Silicon Revision Affected:**Fixed:**

11.4 The RTRIS bit in the UARTRIS register is only set when the interrupt is enabled

Description:

RTRIS
(UARTRIS)
RTIM

UART Interrupt Mask (UARTIM)
RTRIS

UART Raw Interrupt Status

RTIM

Workaround:

RTIM

RTRIS

Silicon Revision Affected:**Fixed:**

12 SSI

12.1 An interrupt is not generated when using μ DMA with the SSI module if the EOT bit is set

Description:

EOT

SSICR1

Workaround:**Silicon Revision Affected:****Fixed:**

13 I2S

13.1 Some bits in the I2SMCLKCFG register do not function

Description:

	RXI	TXI		I2SMCLKCFG
RXI		TXI	RXI	TXI

Workaround:

Silicon Revision Affected:

Fixed:

13.2 I²S SCLK signal is inverted in certain modes

Description:

Workaround:

1. I2S0TXSCK I2S0TXWS
- 2.

Silicon Revision Affected:

Fixed:

14 Ethernet Controller

14.1 Ethernet receive packet corruption may occur when using optional auto-clock gating

Description:

(RCC)

ACG

Run-Mode Clock Configuration

Workaround:

ACG

RCC

Silicon Revision Affected:

Fixed:

14.2 Ethernet packet loss with cables longer than 50 meters


Description:

Workaround:

1.

2.

Figure 2. Recommended Center-Tap Connections



Silicon Revision Affected:

Fixed:

14.3 Ethernet PHY interrupts do not function correctly

Description:

Workaround:

Silicon Revision Affected:

Fixed:

14.4 Encoding error in the Ethernet MAC LED Encoding (MACLED) register

Description:

LED0	LED1	Ethernet MAC LED Encoding (MACLED)
------	------	------------------------------------

Workaround:

Silicon Revision Affected:

Fixed:

15 USB

15.1 USB0ID and USB0VBUS signals are required to be connected regardless of mode

Description:

DEVMODOTG	USB General-Purpose Control and Status (USBGPCS)
-----------	--

Workaround:

USB0VBUS

USB0ID
DEVMOD

USB

General-Purpose Control and Status (USBGPCS)

Silicon Revision Affected:

Fixed:

15.2 Latch-up may occur if power is applied to the VBUS pin but not to VDD

Description:

Workaround:

USB0VBUS

Silicon Revision Affected:

Fixed:

16 PWM

16.1 PWM generation is incorrect with extreme duty cycles

Description:

PWM Load (PWMnLOAD)

PWM0 Compare A (PWM0CMPA)

PWM0CMPA

Workaround:

PWMnLOAD

Silicon Revision Affected:

Fixed:

16.2 Sync of PWM does not trigger "zero" action

Description:

PWM Generator Control (PWM0GENA)

ActZero

PWM Time Base Sync (PWMSYNC)

Workaround:

Silicon Revision Affected:

Fixed:

16.3 PWM "zero" action occurs when the PWM module is disabled

Description:

Workaround:

Silicon Revision Affected:

Fixed:

16.4 PWM Enable Update register bits do not function

Description:

ENUPDn PWM Enable Update (PWMENUPD)

Workaround:

Silicon Revision Affected:

Fixed:

17 Electrical Characteristics

17.1 Momentarily exceeding V_{IN} ratings on any pin can cause latch-up

Description:

\overline{RST} \overline{WAKE}

Figure 3. Incorrect Reset Circuitry






Figure 4. Excessive Undershoot Voltage on Reset




Workaround:

Figure 5. Recommended Reset Circuitry



$\overline{\text{RST}}$

Figure 6. Recommended Voltage on Reset



Silicon Revision Affected:

Fixed:

17.2 Power-on event may disrupt operation

Description:

Workaround:

Figure 7. Configuration of External Regulator





Figure 8. VDDC Sequencing Requirements



Silicon Revision Affected:

Fixed:



IMPORTANT NOTICE

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, modifications, enhancements, improvements, and other changes to its products and services at any time and to discontinue any product or service without notice. Customers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All products are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its hardware products to the specifications applicable at the time of sale in accordance with TI's standard warranty. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by government requirements, testing of all parameters of each product is not necessarily performed.

TI assumes no liability for applications assistance or customer product design. Customers are responsible for their products and applications using TI components. To minimize the risks associated with customer products and applications, customers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any TI patent right, copyright, mask work right, or other TI intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information published by TI regarding third-party products or services does not constitute a license from TI to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of TI information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. Reproduction of this information with alteration is an unfair and deceptive business practice. TI is not responsible or liable for such altered documentation. Information of third parties may be subject to additional restrictions.

Resale of TI products or services with statements different from or beyond the parameters stated by TI for that product or service voids all express and any implied warranties for the associated TI product or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

TI products are not authorized for use in safety-critical applications (such as life support) where a failure of the TI product would reasonably be expected to cause severe personal injury or death, unless officers of the parties have executed an agreement specifically governing such use. Buyers represent that they have all necessary expertise in the safety and regulatory ramifications of their applications, and acknowledge and agree that they are solely responsible for all legal, regulatory and safety-related requirements concerning their products and any use of TI products in such safety-critical applications, notwithstanding any applications-related information or support that may be provided by TI. Further, Buyers must fully indemnify TI and its representatives against any damages arising out of the use of TI products in such safety-critical applications.

TI products are neither designed nor intended for use in military/aerospace applications or environments unless the TI products are specifically designated by TI as military-grade or "enhanced plastic." Only products designated by TI as military-grade meet military specifications. Buyers acknowledge and agree that any such use of TI products which TI has not designated as military-grade is solely at the Buyer's risk, and that they are solely responsible for compliance with all legal and regulatory requirements in connection with such use.

TI products are neither designed nor intended for use in automotive applications or environments unless the specific TI products are designated by TI as compliant with ISO/TS 16949 requirements. Buyers acknowledge and agree that, if they use any non-designated products in automotive applications, TI will not be responsible for any failure to meet such requirements.

Following are URLs where you can obtain information on other Texas Instruments products and application solutions:

Products		Applications	
Amplifiers	amplifier.ti.com	Audio	www.ti.com/audio
Data Converters	dataconverter.ti.com	Automotive	www.ti.com/automotive
DLP® Products	www.dlp.com	Communications and Telecom	www.ti.com/communications
DSP	dsp.ti.com	Computers and Peripherals	www.ti.com/computers
Clocks and Timers	www.ti.com/clocks	Consumer Electronics	www.ti.com/consumer-apps
Interface	interface.ti.com	Energy	www.ti.com/energy
Logic	logic.ti.com	Industrial	www.ti.com/industrial
Power Mgmt	power.ti.com	Medical	www.ti.com/medical
Microcontrollers	microcontroller.ti.com	Security	www.ti.com/security
RFID	www.ti-rfid.com	Space, Avionics & Defense	www.ti.com/space-avionics-defense
RF/IF and ZigBee® Solutions	www.ti.com/lprf	Video and Imaging	www.ti.com/video
		Wireless	www.ti.com/wireless-apps