










[ImageName]

Inspection Pictures	
1	2
	
2	4
	
5	6
	
7	8
	
9	
	



**Disclaimer:** *The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Visit Report does not relieve the Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / item(s) supplied and document(s) submitted. TÜV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any way/ legally responsible for genuineness of the material / item(s) and document(s).*

**Copyright:** *This document is the property of TUV India and should not be reproduced, except in full without the consent of TUV India Pvt. Ltd.*

**TUV IPL (TÜV NORD GROUP):** (REGD. & HEAD OFFICE), 801, Raheja Plaza - I, LBS Marg, Ghatkopar (West), Mumbai – 400086, Maharashtra, India.  
Tel: [+ 91 22 66477000](tel:+912266477000), Email: [inspection@tuv-nord.com](mailto:inspection@tuv-nord.com) Website: [www.tuv-nord.com/in](http://www.tuv-nord.com/in)

**Form No.:** F / INSP / VR / 11 – R9; Revision Date: 19.02.2019

---