

Vehicle Damage Report

Peugeot 108

Generated 2025-06-26 14:46 UTC

Overall Severity: moderate

Repair Complexity: medium

Damaged Parts: 7

Total Estimated Hours: 18

Damage Overview

Part	Location	Severity	Damage Type	Repair Method	Image Ref
Front bumper cover	front	moderate	deformation	repair	image3.jpg #1
Bonnet	front	moderate	deformation	repair	image3.jpg #2
Left headlight	front LH	moderate	crack	replace	image4.jpg #3
Right front fender	front RH	moderate	deformation	repair	image8.jpg #4
Bonnet	front	moderate	deformation	repair	image3.jpg #2
Right headlight	front RH	severe	crack	replace	image5.jpg #4
Left front fender	front LH	moderate	deformation	repair	image8.jpg #5

Damage Details

1. Front bumper cover (front)

Severity: moderate Repair: repair

The front bumper cover exhibits moderate deformation, likely from an impact. The damage is visible across a significant portion of the bumper, affecting its structural integrity.

Ensure alignment is checked post-repair.

2. Bonnet (front)

Severity: moderate **Repair:** repair

The bonnet has moderate deformation, suggesting a frontal impact. The damage affects the bonnet's ability to close properly and may impact aerodynamics.

Check for underlying structural damage.

3. Left headlight (front LH)

Severity: moderate **Repair:** replace

The left headlight has a moderate crack, which may allow moisture ingress and affect light output. The integrity of the headlight is compromised.

Consider replacing the bulb if moisture is present.

4. Right front fender (front RH)

Severity: moderate **Repair:** repair

The right front fender shows moderate deformation, likely from a side impact. The damage may affect the vehicle's appearance and aerodynamics.

Inspect for any hidden damage to mounting points.

5. Bonnet (front)

Severity: moderate **Repair:** repair

The bonnet has moderate deformation, indicating a frontal collision. This damage may hinder the bonnet's functionality and alignment.

Verify the latch mechanism for proper operation.

6. Right headlight (front RH)

Severity: severe **Repair:** replace

The right headlight has a severe crack, significantly impairing its function and potentially allowing water ingress. Replacement is necessary to restore full visibility.

Check electrical connections for damage.

7. Left front fender (front LH)

Severity: moderate **Repair:** repair

The left front fender is moderately deformed, suggesting impact damage. This may affect the vehicle's aesthetic and could lead to rust if not addressed.

Ensure paint is properly matched during repair.

Parts Required for Repair

Category	Part Name	OEM Only	Sub-components	Labour h	Paint h
body panel	front bumper cover	No	mounting brackets, clips	2.5	2.0
lighting	left headlight assembly	Yes	bulbs, wiring harness	1.2	0.0
paint	base coat	No		0.0	1.5
paint	clear coat	No		0.0	1.0
adhesive	bumper adhesive	No		0.0	0.0
fasteners	bumper clips	No		0.0	0.0

Damage Map



Vehicle Photos




1



2



3



4