

Vehicle Damage Report

Peugeot 108

Generated 2025-06-26 00:25 UTC

Overall Severity: moderate
Repair Complexity: medium
Damaged Parts: 7
Total Estimated Hours: 18

Damage Overview

Part	Location	Severity	Damage Type	Repair Method	Image Ref	Description
Front bumper cover	front	moderate	deformation	repair	image3.jpg #1	The front bumper cover exhibits moderate deformation, likely from an impact. The damage is visible across a significant portion of the bumper, affecting its structural integrity.
Bonnet	front	moderate	deformation	repair	image3.jpg #2	The bonnet has moderate deformation, suggesting a frontal impact. The damage affects the bonnet's ability to close properly and

Part	Location	Severity	Damage Type	Repair Method	Image Ref	Description
						may impact aerodynamic
Left headlight	front LH	moderate	crack	replace	image4.jpg #3	The left headlight has a moderate crack, which may allow moisture ingress and affect light output. The integrity of the headlight is compromised
Right front fender	front RH	moderate	deformation	repair	image8.jpg #4	The right front fender shows moderate deformation, likely from a side impact. The damage may affect the vehicle's appearance and aerodynamic
Bonnet	front	moderate	deformation	repair	image3.jpg #2	The bonnet has moderate deformation, indicating a frontal collision. This damage may hinder the bonnet's functionality and alignment.
Right headlight	front RH	severe	crack	replace	image5.jpg #4	The right headlight has a severe crack, significantly impairing its function and potentially allowing water ingress.

Part	Location	Severity	Damage Type	Repair Method	Image Ref	Description
						Replacement is necessary to restore full visibility.
Left front fender	front LH	moderate	deformation	repair	image8.jpg #5	The left front fender is moderately deformed, suggesting impact damage. This may affect the vehicle's aesthetic and could lead to rust if not addressed.

Parts Required for Repair

Category	Part Name	OEM Only	Sub-components	Labour h	Paint h
body panel	front bumper cover	No	mounting brackets, clips	2.5	2.0
lighting	left headlight assembly	Yes	bulbs, wiring harness	1.2	0.0
paint	base coat	No		0.0	1.5
paint	clear coat	No		0.0	1.0
adhesive	bumper adhesive	No		0.0	0.0
fasteners	bumper clips	No		0.0	0.0

Damage Map



Front



Left



Rear




Right

Vehicle Images









© 2025 AutoDamagePro – AI-generated report. Human verification required.