


Plane Gets "Chewed Up" Using Thermal Relief Vias



Plane Remains Intact Using Full Contact Vias