



TODO: Rplace test connector with test pads.

TODO: Extend the pads of the fuses, and proection diods.


TODO: Increase the resistor of the greed +5V LED. It's too bright.




Edge Connector



Isolated DC/DC



ESD Protection



Test Points