

Nombre CFE SUR				Particular <input type="checkbox"/> Flotilla <input checked="" type="checkbox"/>		OdeS		ID: <input checked="" type="checkbox"/>	
Dirección				Ciudad		Estado		Escrito Por Jan	
C.P.		Tel. Fijo		Contacto			Tel. Celular		
Email				Gasolina entrada __LL __3/4 __½ __1/4		Gasolina salida __LL __3/4 __½ __1/4		Recibido Fecha: 18/9/23 AM	
Año 2004		Marca FORD		Modelo COURIER		Color DOCOBZUBZA		Hora: PM	
Km Entrada		Km Salida		VIN		# Económico 69288		Compromiso para Fecha: AM	
169,962				9BFBT3CNS47956071				Hora: PM	
								Salida Fecha: 18/9/23 AM	

Técnico
JUAN
Firma de Supervisión:

☐ ☐ Logos en buen estado
☐ ☐ Exceso de rociado
☐ ☐ Daños por granizo
☐ ☐ Lluvia ácida

The image contains four line drawings of vehicles arranged in a 2x2 grid. The top-left drawing is a station wagon viewed from the rear three-quarter angle. The top-right drawing is a pickup truck viewed from the rear three-quarter angle. The bottom-left drawing is a station wagon viewed from the front three-quarter angle. The bottom-right drawing is a pickup truck viewed from the front three-quarter angle.

FUGA DE AGUA

Firma del Cliente

ECO IMPULSA, S.A. DE C.V.
PUERTO DE ACAPULCO #328, COL. TINIJARÓ, C.P. 58337, MORELIA, MICH.
TELS. (443) 520-5177 / 520-5178

NO 16416