

Recibido	
Fecha:	15/12/22 A/M
Hora:	15:30 P/M
Compromiso para	
Fecha:	A/M
Hora:	P/M
Salida	
Fecha:	16/12/22 A/M
Hora:	2:10 P/M
Técnico	
ISZ acy/s	
Firma de Supervisión	

VARIOS EQUIPOS - INVENTARIO

Cia. Seg.
Tel. Seg.
Siniestro No.
Ajustador

CONDICIONES DE PINTURA

SI	NO		SI	NO	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Decolorada	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Logos en buen estado
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Color no Igualado	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Exceso de rociado
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Exceso de Rayones	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Daños por granizo
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Pequeñas Grietas	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Lluvia ácida
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Carrocería con golpes	<input type="checkbox"/>	<input type="checkbox"/>	_____
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Emblemas completos	<input type="checkbox"/>	<input type="checkbox"/>	_____

The image contains four line drawings of vehicles arranged in a 2x2 grid. The top-left drawing is a station wagon viewed from the rear three-quarter angle. The top-right drawing is a pickup truck viewed from the rear three-quarter angle. The bottom-left drawing is a station wagon viewed from the front three-quarter angle. The bottom-right drawing is a pickup truck viewed from the front three-quarter angle.

Indicaciones del Cliente:

RECHINA BANDA
GOLPETO EN SUSPENSIÓN
TRASERA.

Recibo por

Firma del Cliente

ECO IMPULSA, S.A. DE C.V.
PUERTO DE ACAPULCO #328, COL. TINIJARO, C.P. 58337, MORELIA, MICH.
TELS. (443) 520-5177 / 520-5178

NO 14481