

GARMIN®

AVIATION TRAINING

Garmin GFC 600

Double Checks and Quick Tips

Garmin Aviation Training is intended to provide the best practices for the installation, use and maintenance of Garmin Aviation products. It is incumbent on technicians and pilots to ensure that the instructions contained in the most recent versions of Garmin product manuals, bulletins and notifications are followed.

© GARMIN LTD. OR ITS SUBSIDIARIES. ALL RIGHTS RESERVED.

Objectives

Monday, March 30, 2026

- ✈ After completing this training, you will:
 - ✈ Execute installs with precision by examining the model specific installation documentation.
 - ✈ Understand the Garmin's GMC 605 configuration and how it aids in installation verification.
 - ✈ Better articulate advice by Garmin Autopilot Subject Matter Experts and Certification Team by reading the notes.

Garmin Training Center

training.garmin.com/Saba/Web_spf/NA10P1PRD010/app/catalog/search?searchText=GFC%20600&selectedTab=LEARNINGEVENT

GARMIN Browse

Learning Catalog Enter text to search...

Search Results for "GFC 600"

Request Course Share URL

GFC 600

All Learning Catalog Links Files Videos Pages Discussions Collections Groups Meetings

Learning Event Type Delivery Type Category Language Rating Duration

51 results found for 'GFC 600'

Sort By Relevance

PILOT
GFC™ 600
AUTOPILOT OPERATIONS
00h 09m
Course (1 class)
GFC 600 Autopilot Operations:
Executing Approaches
Not Registered

PILOT
GFC™ 600
AUTOPILOT OPERATIONS
00h 05m
Course (1 class)
GFC 600 Autopilot Operations:
Vertical Navigation
Not Registered

MX
GFC™ 600
AUTOPILOT OPERATIONS
01h 02m
Course (1 class)
GFC 600 Maintenance Training -
Recorded Webinar
Not Registered

PILOT
GFC™ 600
AUTOPILOT OPERATIONS
00h 09m
Course (1 class)
GFC 600 Autopilot Operations:
Controls and Annunciations
Not Registered

PILOT
GFC™ 600
AUTOPILOT OPERATIONS
00h 05m
Course (1 class)
GFC 600 Autopilot Operations:
The Missed Approach
Not Registered

MX
DEALER
HOT TOPICS
01h 05m
Course (1 class)
Flying the Garmin GFC 600
Autopilot - Recorded Webinar
Not Registered

PILOT
GFC™ 600
AUTOPILOT OPERATIONS
00h 05m

MX
GARMIN
TXi/G1275/GFC 600
IN-PERSON OR VIRTUAL

GFC™ 600
01h 00m

MX
Avion HELPS YOU
00h 01m

MX
BEHIND THE PANEL
00h 02m

PILOT
GFC™ 600
AUTOPILOT OPERATIONS
PLAYLIST

✈ Federated GFC 700 Automatic Flight Control System

- ✈ GMC 605(C)
- ✈ GSA 87
- ✈ GSA 80/81
- ✈ GTA 82
- ✈ GI 285
- ✈ Third party integrations




✈ Additions to GFC 600 STC

- ✈ Cessna 421B Golden Eagle
- ✈ Cessna Citation CJ 1 (525A)
- ✈ Piper Cheyenne II (PA-31T)




- ✈ Double check your MDL
 - ✈ Ensure you're using the most recent documentation for your airframe!
- ✈ For every 10 minutes you spend reading the notes on the Model Specific Addendum You'll save an HOUR of troubleshooting your installation!
 - ✈ We never have time to do it 'right' but we always make time to do it again!



Master Drawing List, GFC600 AFCS, Part 23 AML STC	005-01009-01	62	April 1, 2024	Download
Master Drawing List, GFC600 AFCS, Part 23 AML STC	005-01009-01	63	May 1, 2024	Download
Master Drawing List, GFC600 AFCS, Part 23 AML STC	005-01009-01	64	May 1, 2024	Download
Master Drawing List, GFC600 AFCS, Part 23 AML STC	005-01009-01	65	September 1, 2024	Download
Master Drawing List, GFC600 AFCS, Part 23 AML STC	005-01009-01	66	December 1, 2024	Download
Master Drawing List, GFC600 AFCS, Part 23 AML STC	005-01009-01	67	December 1, 2024	Download
Master Drawing List, GFC600 AFCS, Part 23 AML STC	005-01009-01	68	April 1, 2025	Download
Master Drawing List, GFC600 AFCS, Part 23 AML STC	005-01009-01	70	August 1, 2025	Download
Master Drawing List, GFC600 AFCS, Part 23 AML STC	005-01009-01	71	August 1, 2025	Download
Master Drawing List, GFC600 AFCS, Part 23 AML STC	005-01009-01	72	August 1, 2025	Download
Master Drawing List, GFC600 AFCS, Part 23 AML STC	005-01009-01	73	September 1, 2025	Download
Master Drawing List, GFC600 AFCS, Part 23 AML STC	005-01009-01	75	February 1, 2026	Download

✈️ Current MDL is revision 75.

✈️ We've made 6 new revisions in the last 12 months



Garmin

Dealer Resource Center

Products

Orders

Training

Tools & Resources

Home / Search / Manuals

GFC™ 600 Digital Autopilot

GFC-600AP-00

Manuals

468 items found

Keywords or Part Number


Product Version

Filter by Product Version

Clear


Search Filter

PUBLICATION NAME	FILE SIZE	PART NUMBER	DATE	DOWNLOAD
Wiring Diagram, Piper PA-31T Cheyenne		005-W0048-01	SA01844WI MDL Rev 75-72	25 Download
Wiring Diagram, GFC600, Pilatus PC-12		005-W0048-00	SA01844WI MDL Rev 71	Download
Wiring Diagram, GFC600, Pilatus PC-12		005-W0048-00	SA01844WI Rev 70	Download
Wiring Diagram, GFC600, Pilatus PC-12		005-W0048-00	SA01844WI Rev 68-60	222 Download
Wiring Diagram, GFC600, Pilatus PC-12		005-W0048-00	SA01844WI Rev 59-50	2022 Download
Wiring Diagram, GFC600, Pilatus PC-12		005-W0048-00	SA01844WI Rev 49-40	15 Download
Wiring Diagram, Cessna Citation Jet 525A		005-W0048-01	SA01844WI Rev 38-34	Download
Wiring Diagram, Cessna Citation Jet 525A		005-W0048-01	SA01844WI Rev 29-20	Download
Wiring Diagram, Cessna Citation Jet 525A		005-W0048-01	SA01844WI Rev 19-10	Download
Wiring Diagram, Cessna Citation Jet 525A		005-W0048-01	SA01844WI Rev 09-01	24 Download
Wiring Diagram, Cessna Citation Jet 525A		005-W0048-01	Appliance Data	Download
Wiring Diagram, Cessna Citation Jet 525 (CJ1)		005-W0057-00	2 May 1, 2025	Download
Wiring Diagram, Cessna Citation Jet 525		005-W0048-00	1 June 1, 2020	Download
Wire Harness Routing/Instl, GFC600, King Air F90, Tail		005-01009-EZ	1 May 1, 2023	Download
Wire Harness Routing/Instl, GFC600, King Air F90, Tail		005-01009-EZ	2 October 1, 2024	Download
Wire Harness Routing/Instl, GFC600, King Air F90, Cabin		005-01009-EY	1 May 1, 2023	Download
Wire Harness Routing/Instl, GFC600, King Air 200/B200, Tail		005-01009-EK	1 November 1, 2022	Download
Wire Harness Routing/Instl, GFC600, King Air 200/B200, Tail		005-01009-EK	2 May 1, 2023	Download
Wire Harness Routing/Instl, GFC600, King Air 200/B200, Tail		005-01009-EK	3 October 1, 2024	Download
Wire Harness Routing/Instl, GFC600, King Air 200/B200, Cabin		005-01009-EJ	2 November 1, 2022	Download
Wire Harness Routing/Instl, GFC600, King Air 200/B200, Cabin		005-01009-EJ	3 May 1, 2023	Download
Wire Harness Assembly, GFC600, King Air F90, Fam Dwg		320-01616-XX	1 May 1, 2023	Download
Wire Harness Assembly, GFC600, King Air 200/B200, Fam Dwg		320-01610-XX	4 December 1, 2022	Download
Wire Harness Assembly, GFC600, King Air 200/B200, Fam Dwg		320-01610-XX	5 May 1, 2023	Download
STC-TCCA (Canada) SA23-55 (Part 23 SA01844WI)		SA23-55	1 September 1, 2023	Download
STC-TCCA (Canada) SA23-55 (Part 23 SA01844WI)		SA23-55	2 November 1, 2024	Download
STC-EASA Master Minimum Equipment List, GFC600 AFCS		190-01937-36	1 June 1, 2023	Download
STC-EASA Master Minimum Equipment List, GFC600 AFCS		190-01937-36	2 September 1, 2025	Download
STC-EASA (Europe) 10062872 (Part 23 SA01844WI - MDL 71)		10062872	9 October 1, 2025	Download




✈️ Using the product version filter

- ✈️ Offers simplicity for quick reference
- ✈️ Works for all Garmin STC products
- ✈️ Focuses searches on only the most recent documents



✈️ Notes offer a direct insight into the lessons learned by the certification team during initial issuance of the STC


✈️ How many notes does the Piper Cheyenne II Model Specific Addendum offer?



✈️ Notes offer a direct insight into the lessons learned by the certification team during initial issuance of the STC

✈️ How many notes does the Piper Cheyenne II Model Specific Addendum offer?


✈️ 63 (as of Rev 3)



✈️ Let's compare the
Cheyenne II to A36 Bonanza

✈️ On the AML since initial
issuance.

✈️ How many notes?



✈️ Let's compare the
Cheyenne II to A36 Bonanza

✈️ On the AML since initial
issuance.

✈️ How many notes?

✈️ 37

190-01937-04_12.pdf

Garmin Training Center: Course

Adobe Acrobat: PDF edit, convert, sign tools

chrome-extension://efaidnbmnnnbpcapccpcgclefndmkaj/https://static.garmin.com/pumac/190-01937-04_12.pdf?download=true

Try PDF Spaces All tools Edit Convert E-Sign

static.garmin.com / 190-01937-04_12

Share Ask AI Assistant Free Trial Sign In

4. PROTECT TRIMMED ALUMINUM SURFACES BY APPLYING CHEMICAL CONVERSION COATING, MIL-DTL-5541 TYPE II CLASS 3, FOLLOWED BY EPOXY PRIMER MIL-PRF-23377 TYPE 1, CLASS N.

5. THE FOLLOWING PARTS MAY BE SUBSTITUTED FOR AIRCRAFT S/N 6-3254:
-115-02380-10 FOR 115-02380-00 -117-00931-10 FOR 117-00931-00
-115-02382-10 FOR 115-02382-00 -233-20036-10 FOR 233-20036-00
-115-02389-10 FOR 115-02389-00 -233-20035-10 FOR 233-20035-00
-115-02390-10 FOR 115-02390-00 -233-20036-10 FOR 233-20036-00
-117-00929-10 FOR 117-00929-00
-117-00930-10 FOR 117-00930-00

6. SEE 190-01937-00 INSTALLATION MANUAL FOR ADDITIONAL SONALERT DETAILS. IF INSTALLED, THE SONALERT MUST BE IN THE GLARSHIELD IN A LOCATION THAT WILL BE FREE FROM OBSTRUCTION. DRILL 1.25" HOLE, INSERT THE SONALERT BODY, PIN 013-00636-00, THROUGH THE HOLE AND THREAD ON THE KNURLED NUT.

7. G1 285 IS REQUIRED IF ANY PART OF THE GMC 605 DISPLAY IS OUTSIDE THE AREA DESIGNATED FOR MOUNTING, AND MUST BE LOCATED WITHIN THE PRIMARY FIELD OF VIEW. SEE INSTALLATION MANUAL 190-01937-00 FOR G1 285 MOUNTING INSTRUCTIONS. IF THE AIRCRAFT IS EQUIPPED WITH A GARMIN GDL, NO GDL IS REQUIRED.

8. IF NO HOLE EXISTS, DRILL HOLE IN YOKE AS SHOWN. DEBURR EDGES TO ENSURE NO SHARP EDGES.

9. ROUTE COIL CORD THROUGH HOLE AND GROMMET IN INSTRUMENT PANEL. INSPECT CONDITION OF EXISTING GROMMET, REPLACE IF NECESSARY. SECURE BEHIND PANEL WITH EXISTING FASTENER HARDWARE AND MS21919WDS CLAMP.

10. MOUNT THE GO AROUND SWITCH IN THE THROTTLE CONTROL. ROUTE AND PROTECT WIRING SIMILAR TO THE PREVIOUS INSTALLATION. THE THROTTLE HANDLE MUST BE LABELED "GO AROUND".

11. USE 165-04521-00 PLACARDS, TRIM TO FIT. FIELD FABRICATED PLACARDS MAY BE USED, SEE INSTALLATION MANUAL 190-01937-00 FOR REQUIREMENTS.

12. SEE INSTALLATION MANUAL 190-01937-00 FOR WIRING DETAILS. ALL SOLDER CONNECTIONS TO BE MADE IN ACCORDANCE WITH THE AS461.

13. MAINTAIN A MINIMUM OF 1.50 EDGE DISTANCE. INSTALLED SCREW IS TO BE FLUSH WITH SEAT TRACK. CLEAN UNDERSIDE OF SEAT TRACK IN THE AREA WHERE THE ROLL SERVO BRACKET CONTACTS TO ACHIEVE ELECTRICAL CONTACT PER NOTE 1.

14. ASSEMBLE AND TORQUE NUT TO 25 ± 5 IN-LBS. INSERT COTTER PIN INTO HOLE ON SHAFT OF SERVO. SECURE IN PLACE WITH COTTER PIN IN ACCORDANCE WITH AC 43-13-18.

15. POSITION OF STANDOFFS VARY, SEE SPECIFIC SERVO DETAIL FOR STANDOFF INSTALLATIONS.
15.1. TORQUE 214-10007-01 STANDOFF TO 6-8 IN-LBS.
15.2. TORQUE 210-10004-04 OR MS21044-NUT NUT TO 6-8 IN-LBS.

16. 115-02390-00 LEFT, PITCH SERVO SHELF SUPPORT LEG NOT SHOWN, INSTALLATION MIRROR OF 115-02389-00 IN SECTION 6-G.

17. SEE INSTALLATION MANUAL 190-01937-00 FOR GROUND STUD BUILD UP.

18. DELETED

19. THE FOLLOWING ITEMS MAY BE RETAINED IF EXISTING:
• COIL CORD* AND ATTACHING CLAMP/HARDWARE
• TRIM SWITCH*
• CONTROL WHEEL SWITCH PLATE
*SEE INSTALLATION MANUAL 190-01937-00 FOR SPECIFIC REQUIREMENTS.

20. SET THE SERVO CABLE TENSION TO 15 ± 3, 10 LBS AT 70° CORRECT TO CABLE TENSION CHART FOR TEMPERATURE.

21. PRIOR TO ASSEMBLY, CLEAN CABLE AND CLAMP TO REMOVE ANY GREASE OR RESIDUE. USING A CALIBRATED TORQUE WRENCH, TIGHTEN NUTS TO 45 IN-LBS. THEN IF NECESSARY, TIGHTEN NUT TO NEXT CALIBRATION TO ALIGN HOLE FOR COTTER PIN. APPLY TORQUE SEAL TAMPER INDICATOR AT INTERSECTION OF CABLE AND CLAMP.

22. THROUGHOUT THE FULL RANGE OF THE CONTROL SURFACE, MAINTAIN A MINIMUM OF 90° OF CABLE WRAP AROUND THE CAPSTAN TO NOT ALLOW THE BALL TO EXIT.

27. UNLESS OTHERWISE SPECIFIED, TORQUE AN3 BOLTS (.1900-32 UNF-2A) TO 20-25 IN-LBS.

28. 011-04339-00 MOUNTING KIT CONTAINS 011-04477-00 AND 011-04478-00 KITS.

29. AIRCRAFT MAY HAVE AN ELEVATOR CABLE PULLEY ASSEMBLY AT F.S. 233.50 AND A PITCH TRIM CABLE NEAR F.S. 207.00 THAT ARE PART OF AN EXISTING AUTOPILOT. REMOVAL OF THE PULLEY ASSEMBLY IS REQUIRED. IF THE PITCH TRIM CABLE WRAPS AROUND THE SERVO CAPSTAN, THAT SECTION OF CABLE MUST BE REMOVED AND REPLACED WITH THE PITCH TRIM CABLE FOUND IN THE AIRCRAFT ILLUSTRATED PARTS CATALOG.

30. USE TIE WRAPS TO SECURE THE ENDS OF THE SPIRAL WRAP AND PREVENT THE MATERIAL FROM SPREADING.

31. MS35207-263 SCREWS OR AN3-4 BOLTS MAY BE USED IN PLACE OF MS16998-29 SOCKET HEAD CAP SCREWS.

32. ENSURE AILERON CONTROL CABLE AND ROLL SERVO BRIDAL CABLE, INCLUDING CABLE CLAMP, PASS THROUGH THE EXISTING AIRCRAFT INTERIOR PANEL WITH MINIMUM 0.5 INCH CLEARANCE. ADD OR ENLARGE EXISTING HOLE IN LH SIDE PANEL ACCORDINGLY.

33. ROLL SERVO INSTALLED USING 115-02607-00 BRACKET, 115-02608-00 BRACKET AND 115-02620-00 PLATE MUST USE GMC 605 SOFTWARE VERSION 303201 (OR NEWER), GARMIN PART NO. 006-83032-01.

34. INSTALLATION OF 115-03005-00, 115-03006-00 AND 115-03105-00 LEFT PITCH SERVO SHELF SUPPORTS NOT SHOWN, INSTALLATION MIRROR OF 115-03004-00, 115-03003-00 AND 115-03106-00 IN SECTION W-W.

35. NOTE DELETED.

36. 115-03004-00 AND 115-03006-00 NOT TO BE USED FOR NEW INSTALLATIONS.

37. EQUALLY SPACE FASTENERS, MAINTAINING MINIMUM 2X EDGE DISTANCE AND MINIMUM 4X PITCH, UNLESS OTHERWISE SPECIFIED.

SERVO CABLE TENSION CHART

CABLE TENSION, LBS

TEMPERATURE, °F

MODEL SPECIFIC INFORMATION

TRIM SYSTEM RUN TIME, (STOP TO STOP)	18-21 SECONDS
MAX SPEED (OVERSPEED PROTECTION)	194 KTS
MIN SPEED (UNDERSPEED PROTECTION)	80 KTS
FLIGHT DIRECTOR COMMAND BAR GO AROUND PITCH UP ATTITUDE	7°
ESP ROLL INDICES	45° LEFT AND RIGHT

SEE INSTALLATION MANUAL 190-01937-00 FOR POST-INSTALL CHECKOUT

GARMIN®

Garmin Ltd. or its subsidiaries
c/o Garmin International, Inc.
1200 E. 15th Street
Olathe, Kansas 66062 U.S.A.

SIZE B

DWG. NO. 190-01937-04

REV. 12

SCALE: NONE

SHT. 2 OF 26

✈️ Let's compare the Cheyenne II to A36 Bonanza

✈️ On the AML since initial issuance.

✈️ How many notes?

✈️ 37

✈️ Always Read the Notes!





Spot the difference: (picture of GMC 605 and GMC 605C)
Which GMC is the 'non-color' version??

- A. GMC 605 (Top)
- B. GMC 605C (Bottom)

SPOT THE DIFFERENCE

GMC605 (monochrome) vs. GMC605C (color)





NOTES

NOTE: Loading Monochrome SW to a Color GMC (vise versa) may brick the unit, requires returning unit for repair.

Loading the wrong software will appear as though the GSA's failed to load.

- ✈️ GMC 605 (monochrome) vs GMC 605C (color)
- ✈️ GMC 605 software version displayed bottom right of splash screen
- ✈️ GMC 605C software version displayed bottom right of score board during PFT

Software Downloads

53 items found.

Type All

Keyword(s)

Clear

Search Filter

NAME	FILE SIZE	TYPE	PUBLISH DATE ↑	PUBLISH END DATE	STATUS	
+ GFC 600/GMC 605 Software, STC SA01844WI MDL 70+ (006-B2968-xx thru 006-B3681-xx) a.zip	75.62 MB	Software Updates	August 15, 2025		✓	Select Action ▾
+ GFC 600/GMC 605 Software, STC SA01844WI MDL 70+ (006-B3752-xx thru 006-B4490-xx) b.zip	71.86 MB	Software Updates	August 15, 2025		✓	Select Action ▾
+ GFC 600/GMC 605C Software, STC SA01844WI MDL 70+ (006-B4466-xx thru 006-B4699-xx) ac.zip	70.60 MB	Software Updates	August 15, 2025		✓	Select Action ▾
+ GFC 600/GMC 605C Software, STC SA01844WI MDL 70+ (006-B4700-xx thru 006-B4863-xx) bc.zip	81.51 MB	Software Updates	August 15, 2025		✓	Select Action ▾
+ GFC 600/GMC 605 Software, Part 23 AML STC SA01844WI MDL 68+ (006-B2968-xx thru 006-B3681-xx) a.zip	75.62 MB	Software Updates	May 2, 2025		✓	Select Action ▾
+ GFC 600/GMC 605 Software, Part 23 AML STC	75.98 MB	Software	May 2, 2025		✓	Select Action ▾


- ✈ PFT Fails (P-Trim Fail, YD Fail, ESP Fail*)
- ✈ PFT Hangs-up or never passes (PFT, NO ATT, or ESP Off*)
 - ✈ The usual suspects:
 - ✈ Wiring – the #1 & #2 cause for PFT failures in new installations
 - ✈ Software – Incorrect version or incorrectly loaded (monochrome vs color)
 - ✈ Hardware – Actual failed LRU, installed in incorrect position or not installed
 - ✈ Configuration – Expected input not present or invalid




GMC 605C



- ✈ ESP annunciators during PFT are suppressed.
- ✈ ESP OFF or ESP FAIL will not be displayed as seen on GMC 605








- ✈️ PRODUCT > SERVOS
- ✈️ Are all of my servos reporting?
- ✈️ Control & Monitor boards communicating?
- ✈️ Serial number check
- ✈️ Servo location



- ✈️ PRODUCT > SERVOS
- ✈️ Are all of my servos reporting?
- ✈️ Check ID Strapping?
- ✈️ Check wiring?
- ✈️ Check Connections?






- ✈ GFC > SERVOS > P/R/Y/PT > MON/CTL
- ✈ Servo ID straps
- ✈ AP Disconnect state (normally closed, PIN 17, voltage)
- ✈ Servo PFT checks








✈ I/O > RS485

✈ Status ✓ does not mean it is correct data

✈ There is a wire in the port



✈ I/O > RS485

✈ PC-12 Customer States: Intermittent AP FAIL


- ✈ While verifying this, the technician noticed the results for PROGRAM 1-4 & AP DISC would momentarily blank then show "?", PFT would read "NO DATA".
- ✈ After about 3 seconds, all indications would normalize. This would repeat every 35-45 seconds.




✈ I/O > RS485

✈ PC-12 Customer States: Intermittent AP FAIL

- ✈ Monitored I/O 485 page. Noticed the status ✓ blink to x momentarily
- ✈ Rang out 485 AGAIN while manipulating harnesses. FOUND THE SHORT
- ✈ De-pinned terminal block, found mangled wire making contact to ground inside the terminal block








NOTES

NOTE: The I/O Channel number and/or name may not be the same as listed in the GFC 600 IM. Nomenclature on the GMC Screen may not match the diagram.

Ensure that the GMC 605 inputs are wired as shown in the Install Manual Addendum!

- ✈ I/O > DISCRETES > IN
- ✈ AP Disconnect
- ✈ Flaps, CWS, Stall Warning, Landing Gear, Pilot/CoPilot etc.



AP Disconnect Switch

✈ In 1: AP Disc Normally Closed

✈ P6051 Pin 17, Voltage

✈ Y when relaxed, N when depressed




AP Disconnect Switch


✈ In 11: AP Disc Normally Open

✈ P6051 Pin 37, Ground

✈ N when relaxed, Y when depressed







✈ Is the system Receiving
VALID ADC & AHRS?

✈ Internal:

✈ GMC internal AHRS sensor

✈ External: (if present)

✈ HSDB, A429

✈ Handshake:

✈ Agreement between GMC
cal data & sensors



✈ CJ2 Cessna 525A TXi GFC600

✈ GMC605 Color Only

✈ 2x HSDB Connections
(port 2 & 3)

✈ Does NOT use internal AHRS

✈ ADC/AHRS External 1 & 2 via
ARINC 429 from GSU75 #1 & #2

✈ Specific Install Manual
Addendum & Wiring Diagram



✈️ Customer States:

✈️ Textron 525A CJ2:

✈️ New Install GFC600 Does not pass or “Hangs” PFT

✈️ Troubleshooting:

- ✈️ Wiring
- ✈️ Hardware
- ✈️ Software
- ✈️ Configuration




✈️ Fault & Assert logs showed loss of or invalid AHRS failures

✈️ GFC > AHRS > EXT 1 & 2

✈️ Matching, Valid data

✈️ Where does the GMC get this info?

✈️ ARINC 429 Inputs



✈ I/O > 429 > IN

✈ CH1 AHRS1 (GSU75 #1) = X

✈ How are we getting valid AHRS data with failed 429?



✈ Check your wiring!



- ✈️ Installer States: Swapped GSU 1 & 2
 - ✈️ X stayed on AHRS 1 = Conclusion: wiring
- ✈️ Swapped 429 wires at GMC
 - ✈️ X moved to AHRS 2 = Conclusion: Correct, it's wiring
- ✈️ Replaced wire from GSU1 to GMC
 - ✈️ X on 429 AHRS 1 = Wait What?!



- ✈️ Asked for pictures of GMC & GSU connectors
 - ✈️ Found pins not listed in CJ2 Wiring Diagram
 - ✈️ GSU75 has 2 AHRS out #3's (P751 Pins 8/9 & 28/29)
 - ✈️ They're internally jumped for the duplicate output.
- ✈️ Dealer decided to run an extra 429 from GSU1 to the GTX345R.
 - ✈️ GTX was shorting out the 429, causing the loss of AHRS to the GMC.



✈️ Assert Logs:

✈️ Downloadable to from Configuration Mode (SYS page)

✈️ 4G-8G Sandisk USB stick

✈️ Garmin USB-A to Micro USB-A dongle 320-00726-01

✈️ Establish a discussion with FSE before send Assert Logs!



Where are the required documents for GFC install located?

- A. Equipment List
- B. STC Approved Models List
- C. Master Data List
- D. AML STC Installation Manual



Where are the required documents for GFC install located?

- A. Equipment List
- B. STC Approved Models List
- C. Master Data List
- D. AML STC Installation Manual



What is the difference between GMC 605 and GMC 605C?

- A. GMC 605 has LED's on the left of the bezel
- B. GMC 605C doesn't have Mode Select Outlines
- C. Software loading procedures
- D. The software part numbers



What is the difference between GMC 605 and GMC 605C?

- A. GMC 605 has LED's on the left of the bezel
- B. GMC 605C doesn't have Mode Select Outlines
- C. Software loading procedures
- D. The software part numbers



In which Garmin document do I find my Aircraft Specific Software for GFC 600?

- A. Equipment List
- B. STC Approved Models List
- C. Master Data List
- D. AML STC Installation Manual



In which Garmin document do I find my Aircraft Specific Software for GFC 600?

- A. Equipment List
- B. STC Approved Models List
- C. Master Data List
- D. AML STC Installation Manual



True or False: I attended the GFC 600 Training in the RED Room

- A. True
- B. False

Summary

Monday, March 30, 2026

- ✈ Quick Tip for searching thru Garmin Documents on the Dealer Resource Center.
- ✈ We walked thru several scenarios provided by Field Service where a quick double check of the installation documentation would save the dealership and installer time and effort.

For Reference Only
Not for Public Distribution

LOKAND

V21-1095
21A-392





Any Questions?

For Reference Only
Not for Public Distribution



Thank You!

✈ Chris Hendrix

✈ Senior Aviation Maintenance Instructor

✈ Garmin Aviation Training

✈ Aviation.training@garmin.com