

STAR PROPERTY MANAGEMENT

Southwest Texas Residential Portfolio

Make-Ready QC Inspection Report - Las Palmas Unit 8D

Residential Property Management - Southwest Texas Region

UNIT CONDITION / QC INSPECTION REPORT

Report No.: SPM-2026-MR-8D-QC

Property:

Las Palmas Apartments - Unit 8D

Date of Inspection: July 14, 2026

Conducted By:

Jaime Salinas, Maintenance Lead

Purpose:

Post-Make-Ready Quality Control Walkthrough

Related Turn:

Las Palmas 8D Vacancy Turnover

SECTION 1 - SUMMARY

I conducted a full quality control walkthrough of Las Palmas Unit 8D today, following completion of all scheduled make-ready work for this turn: in-house drywall patching, kitchen faucet replacement, bedroom touch-up painting, professional carpet cleaning, and a full housekeeping deep clean. The unit is in substantially rent-ready condition, and the work completed by the in-house team and the carpet vendor is reflected in the overall cleanliness and functionality of the space. Two minor punch-list items were identified during the walkthrough - a scuffed baseboard along the hallway wall and a missing outlet cover plate in the bedroom. Both items are simple, low-effort corrections that do not prevent the unit from being shown to prospective tenants, but must be resolved before any move-in date is confirmed. Findings have been posted to the #make-ready channel with John Smith tagged for follow-through.

SECTION 2 - DETAILED FINDINGS

2.1 ENTRY / FRONT DOOR AREA

Condition Observed: The front door operates correctly - it swings freely, the deadbolt engages and releases without sticking, and the door sweep seats fully against the threshold with no visible gap. The door frame shows no damage or splitting. The transition between the exterior threshold and the interior flooring is secure with no lifting edges.

Issues / Follow-Up: No issues observed. The entry area is clean and move-in ready.

2.2 HALLWAY

Condition Observed: Drywall repairs performed earlier in the turn have fully cured. The patched sections are sanded flush with the surrounding wall surface, and the repaint blends acceptably with the adjacent wall field. Sheen is consistent. The hallway carpet was serviced by the cleaning vendor and no staining or odor remains.

Issues / Follow-Up: A surface scuff is present on the baseboard along the right-hand wall, located roughly midway down the hallway. The damage is limited to the paint and finish layer - the baseboard itself is

structurally intact with no splits, separation from the wall, or missing sections. The most likely cause is incidental contact from equipment or materials during the make-ready work. A touch-up with matching baseboard paint will fully resolve this item; estimated time is under thirty minutes.

2.3 KITCHEN

Condition Observed: The replacement kitchen faucet is properly installed. Supply connections showed no dripping at the valves or at the aerator over a two-minute flow test, and the drain clears without pooling. Cabinet interiors and drawer boxes are free of debris and clean. Countertops are wiped down with no staining. The range burners ignite and the oven door closes flush against the gasket. The deep clean is evident throughout: the range hood filter is free of grease buildup, the microwave interior is spotless, and the sink basin is polished.

Issues / Follow-Up: No issues observed. The kitchen is rent-ready.

2.4 BATHROOM

Condition Observed: Tile and grout surfaces are clean throughout. The toilet seat is stable, the flush mechanism cycles completely, and the tank refills and shuts off without running. The vanity faucet delivers adequate pressure and the drain is clear. The tub and shower surround are free of soap scum, and the caulk line at the tub deck is intact with no peeling or mold present.

Issues / Follow-Up: No issues observed. All plumbing fixtures are functional and the bathroom is clean.

2.5 BEDROOM

Condition Observed: Touch-up paint on the bedroom walls has dried completely and the finish is consistent. The carpet was included in the professional cleaning service and shows no remaining staining or odor. Closet doors slide on track and the closet interior is clean and empty. The ceiling fan runs smoothly on all three speed settings with no wobble or noise.

Issues / Follow-Up: One duplex electrical outlet on the east wall is missing its cover plate. The outlet box and wiring are not hazardously exposed, but the absence of the cover plate is a code-required safety item and a cosmetic deficiency that must be corrected before move-in. A matching standard cover plate should be pulled from the maintenance supply room and installed. This is a five-minute task.

2.6 WINDOWS AND BLINDS

Condition Observed: I checked all windows in the unit. Each window opens, closes, and latches securely. Window seals appear intact with no fogging between panes. Blinds are present at all windows; slats are free of breaks or significant warping, and the lift cords operate without binding or fraying.

Issues / Follow-Up: No issues observed.

2.7 HVAC AND THERMOSTAT

Condition Observed: The thermostat responds correctly in both heating and cooling modes. Cool air delivery from the supply registers is consistent with normal system operation. I checked the return air filter - it is a recently replaced, clean filter. No unusual sounds or odors were detected from the air handler during operation.

Issues / Follow-Up: No issues observed. The HVAC system is performing within normal parameters.

2.8 GENERAL INTERIOR - WALLS, CEILINGS, AND LIGHTING

Condition Observed: Ceiling surfaces throughout the unit are clean and free of water stain rings, peeling texture, or cracks. All light fixtures - kitchen, hallway, bathroom, and living room - illuminate with working bulbs. Wall surfaces not otherwise addressed in prior subsections are clean and free of holes or heavy marking beyond what was already repaired during the turn.

Issues / Follow-Up: No additional issues observed beyond the hallway baseboard scuff documented in Section 2.2.

2.9 PATIO AND BACK DOOR

Condition Observed: The sliding patio door glides along its track without resistance and the locking bar is present and engages properly. The patio slab is swept clean. No debris, personal property, or trash was found in or adjacent to the patio area.

Issues / Follow-Up: No issues observed.

SECTION 3 - RECOMMENDATIONS AND NEXT STEPS

1. HALLWAY BASEBOARD TOUCH-UP

John Smith should apply matching baseboard paint to the scuffed section on the right wall of the hallway. Paint stock for this building is kept in the maintenance supply room. This item should be completed within one business day of this report.

2. BEDROOM OUTLET COVER PLATE INSTALLATION

John Smith should retrieve a standard duplex outlet cover plate from maintenance inventory and install it on the east-wall outlet in the bedroom. This must be done before any showing or move-in appointment is finalized, as it is a required safety correction.

3. SPOT-CHECK AFTER PUNCH-LIST COMPLETION

Once both items above are resolved, I recommend a brief secondary visual confirmation of the two specific locations - the hallway baseboard and the bedroom outlet - to verify completion before the unit status is marked rent-ready in the make-ready tracker. A full re-inspection is not required; the property manager on duty or John Smith can perform this check.

4. LEASING PIPELINE ADVANCEMENT

Brooke Phillips and the leasing team may proceed with scheduling showings for Las Palmas 8D. The unit's overall condition supports active marketing. The two punch-list items are minor and will be corrected in advance of any confirmed move-in.

5. MAKE-READY RECORD UPDATE

The Las Palmas 8D make-ready record should be updated to reflect that the QC inspection is complete, two punch-list items are open and assigned to John Smith, and that the turn is pending final close-out upon confirmation of those corrections.

Report prepared by: Jaime Salinas, Maintenance Lead Star Property Management - Southwest Texas Region

Date Issued: July 14, 2026

Distribution: #make-ready (Slack) - John Smith tagged for punch-list action

Information copies: Carlos Mendez (Property Manager), Brooke Phillips (Leasing Coordinator)