

STAR PROPERTY MANAGEMENT

Southwest Texas Residential Portfolio

Unit Condition Report - QC Inspection, Las Vistas Unit 9D

Unit Condition Report - Quality Control Inspection

Report No.: SPM-QC-2026-0519-9D

Date of Inspection: May 19, 2026

Conducted By: Jaime Salinas, Maintenance Lead

Subject: Las Vistas Apartment Community - Unit 9D Make-Ready Turnover, Final QC Walkthrough

Status Following Inspection: QC - Rework Needed

I. EXECUTIVE SUMMARY

I conducted a full quality-control walkthrough of Unit 9D at Las Vistas on May 19, 2026, following the completion of all scheduled make-ready work items, including drywall patching, interior painting, disposal and dishwasher replacement, carpet cleaning, and a full deep housekeeping pass. The unit is in substantially move-in-ready condition, and the vast majority of completed work meets Star Property Management's turnover standards. One deficiency was identified: a dried paint drip on the baseboard trim in the hallway that was not corrected during the original paint phase. This item must be remediated before the unit can be advanced to a cleared status. All other areas and systems passed inspection without exception.

II. DETAILED FINDINGS

2.1 ENTRY / FOYER

Condition Observed: The front door hardware is clean and operates correctly; the deadbolt and handle set engage and release smoothly with no binding. The entryway flooring transition strip is secured flat with no lifting at the edges. The interior face of the front door was wiped down and is free of scuffs or paint overspray.

Issues / Follow-Up: No issues observed.

2.2 HALLWAY

Condition Observed: The hallway walls and ceiling received fresh paint as part of the make-ready scope. Wall surfaces present evenly at eye level and above - coverage is uniform, with no roller holidays or lap lines detected. However, I observed a paint drip on the face of the baseboard trim at roughly the midpoint of the hallway corridor. The drip has fully dried and hardened into a raised bead that is plainly visible under normal lighting conditions. This finish defect was not remediated during the paint phase and falls below the acceptable move-in standard.

Issues / Follow-Up: Rework required. The dried drip must be sanded flush with the trim surface, cleaned of dust, and spot-painted with the matching trim color. The repaired section must be allowed to cure fully before a secondary QC check is performed. This is the sole item preventing clearance of the unit.

2.3 LIVING ROOM

Condition Observed: Freshly painted walls show consistent sheen and full coverage throughout the living room. Baseboards along all four walls are clean, smooth, and free of drips or scuff marks. The ceiling fan was cleaned and operates without wobble or audible vibration at all speed settings. Window sills, blinds, and the sliding door track are dust-free and functioning.

Issues / Follow-Up: No issues observed.

2.4 KITCHEN

Condition Observed: The replacement dishwasher has been installed level and flush with the cabinetry. I ran a short cycle and confirmed that the door latch, wash, and drain functions all operate correctly, with no moisture present at the supply line or drain connection afterward. The replacement garbage disposal activates immediately upon switch actuation, runs quietly, and the splash guard is properly seated with no wobble. Countertops, cabinet faces, drawer interiors, and the range and hood are clean with no grease residue or debris remaining.

Issues / Follow-Up: No issues observed.

2.5 BATHROOMS (PRIMARY AND SECONDARY)

Condition Observed: Both bathrooms received a thorough deep clean. Tile and grout surfaces are free of mildew and soap scum. Toilet bowls, tank exteriors, and vanity tops are clean. Caulk lines at the tub deck and shower surround are intact with no cracking, separation, or mold present. Exhaust fans in both bathrooms were wiped out and confirmed to pull adequate airflow. All faucets were tested for both hot and cold supply; flow is appropriate, and no drips were observed at the spout or at the supply angle stops beneath the vanities.

Issues / Follow-Up: No issues observed.

2.6 BEDROOMS

Condition Observed: Both bedrooms carry fresh paint applied during the make-ready scope. I inspected the baseboards in each bedroom carefully and found the trim surfaces to be clean, smooth, and free of any paint drips or finish defects. Closet interiors are clean, and rod mounting brackets are secure with no looseness. Window latches engage fully in both rooms.

Issues / Follow-Up: No issues observed.

2.7 CARPET AND HARD FLOORING

Condition Observed: Carpet cleaning was completed ahead of the housekeeping pass. The carpeted areas throughout the unit are visibly clean, free of staining, and carry no residual odor. Pile appears properly groomed. Hard flooring surfaces in the kitchen and bathrooms are clean with no adhesive residue, streaking, or damage at the seams or perimeter edges.

Issues / Follow-Up: No issues observed.

2.8 HVAC AND MECHANICAL

Condition Observed: I confirmed the air handler and thermostat are operational. The system brought the unit down to the thermostat set point within a normal cooling window during the inspection. The return air filter was replaced as part of the make-ready scope and is clean and properly seated in the filter rack. Supply registers throughout the unit are free of dust accumulation and delivering airflow evenly.

Issues / Follow-Up: No issues observed.

2.9 GENERAL CLEANLINESS AND HOUSEKEEPING

Condition Observed: The deep housekeeping pass was completed prior to this QC visit. Interior surfaces throughout - walls, light fixtures, appliances, cabinets, and flooring - reflect a cleaning effort consistent with Star Property Management's move-in presentation standard. No debris, construction materials, or leftover supplies were found anywhere in the unit. The unit is otherwise ready to show and occupy pending resolution of the single rework item noted above.

Issues / Follow-Up: No issues observed beyond the hallway baseboard paint defect documented in Section 2.2.

III. RECOMMENDATIONS AND NEXT STEPS

1. Hallway Baseboard Rework - Required Before Clearance: The dried paint drip on the hallway baseboard trim should be assigned immediately to the painter or lead maintenance. The correct repair procedure is to sand the drip flush with the surrounding trim face, remove sanding dust, and apply a spot coat of the matching trim paint. No other work in the unit needs to be disturbed for this repair. 2. Make-Ready Record Update at Rework Completion: Once the baseboard repair is finished, the responsible technician should update the Las Vistas Unit 9D Make-Ready Turn record to reflect that the rework item has been addressed, so I can be notified and proceed with a secondary QC check of that specific area. 3. Secondary QC Pass on Hallway Trim: Given that only one item requires rework, the follow-up inspection will be focused and brief - limited to confirming the hallway baseboard repair meets finish standards before the turn record is advanced to a cleared status. 4. Team Coordination via #make-ready: I have posted the findings from this inspection in the #make-ready Slack channel so that John Smith, Randy Jones, and Isela Juarez are aware of the single open item and can move the rework forward without waiting on a formal written hand-off. 5. Leasing and Owner Relations Awareness: Brooke Phillips and Lisa Smith should factor the brief rework period into any active scheduling conversations tied to Unit 9D so that a prospective resident is not brought in for a move-in walkthrough until the unit carries a cleared QC status.

IV. CERTIFICATION

I certify that this report accurately reflects the conditions I personally observed during the quality-control walkthrough of Las Vistas Unit 9D conducted on May 19, 2026. Jaime Salinas Maintenance Lead - Star Property Management May 19, 2026