

STAR PROPERTY MANAGEMENT

Southwest Texas Residential Portfolio

Unit Condition / QC Inspection Report - Las Vistas Unit 9D

UNIT CONDITION / QC INSPECTION REPORT

Report Title:

Unit Condition / QC Inspection - Las Vistas, Unit 9D

Report No.:

SPM-QC-2026-051902-9D

Date Conducted:

May 19, 2026

Conducted By:

Jaime Salinas, Maintenance QC Inspector

Subject:

Make-Ready Turnover - Las Vistas, Unit 9D

Status After QC: QC - Rework Needed

SUMMARY

I conducted a full quality-control walkthrough of Las Vistas Unit 9D today, May 19, 2026, following the completion of the make-ready scope - which included drywall repair, interior painting, carpet cleaning, a thorough housekeeping deep clean, and appliance swap-outs covering the dishwasher and garbage disposal. The unit presents well overall, and the large majority of finished work meets Star Property Management's make-ready standard. One item did not clear inspection: a paint drip on the hallway baseboard trim requires correction before the unit can be released. All other areas and systems I examined are confirmed pass-ready. The Make-Ready Turn record has been updated to QC - Rework Needed status and the finding has been communicated to the #make-ready channel.

DETAILED FINDINGS

-

1. ENTRY / FOYER

-

Condition Observed: The entry door operates correctly - the deadbolt, knob latch, and door sweep all function as expected. The threshold plate is clean and undamaged. Walls and ceiling in the foyer show an even paint finish with no holidays, roller marks, or missed cut-in lines at the ceiling.

Issues / Follow-Up: No issues observed. The entry and foyer area passes QC.

-

2. HALLWAY - WALLS, CEILING, AND BASEBOARD TRIM

-

Condition Observed: Hallway walls and ceiling received fresh paint as part of the make-ready scope, and the field coat and ceiling line are uniform throughout. However, on the baseboard trim along the right-hand wall of the hallway approximately eighteen inches from the bedroom doorframe - I observed a dried paint drip roughly one and a half inches in length running down the face of the trim. The drip has fully cured and will require light sanding before a touch-up coat can be applied cleanly to the surface.

Issues / Follow-Up: This defect is the sole reason the unit is being held at QC - Rework Needed status. The affected trim section must be lightly sanded, wiped free of dust, and spot-painted to match the surrounding baseboard color before a re-inspection can be scheduled. No other wall or ceiling defects were noted anywhere in the hallway.

-

3. LIVING ROOM AND DINING AREA

-

Condition Observed: The living and dining spaces show a consistent, clean paint finish across all four walls and the ceiling. Outlets, switch plates, and cover plates are properly seated and free of paint overspray. Window blinds are in place and tilt and raise without binding. The carpet in this area - cleaned as part of the turn - is free of visible stains, detectable odor, and matting; the pile is well-groomed and uniform in color across the full expanse of the room.

Issues / Follow-Up: No issues observed. The living and dining area passes QC.

-

4. KITCHEN - APPLIANCES, FIXTURES, AND SURFACES

-

Condition Observed: The replacement dishwasher and new garbage disposal installed during the earlier phase of the make-ready were both tested during today's walkthrough. The dishwasher door seal is intact, the door latch catches cleanly, and a short run cycle confirmed the unit fills, agitates, and drains without any leaking at the base or the supply connection. The disposal activates immediately on the wall switch, runs without abnormal vibration or noise, and the splash guard is correctly seated. Cabinet interiors and drawer tracks were wiped clean during the deep clean; no grease residue or debris remains. Countertops are free of cracks, stains, or adhesive residue, and the sink basin and faucet are clean with a drain that clears freely.

Issues / Follow-Up: No issues observed. Kitchen appliances, fixtures, and surfaces pass QC.

-

5. BATHROOMS - FIXTURES, SURFACES, AND VENTILATION

-

Condition Observed: I inspected both the primary bathroom and the hallway half-bath. Toilet bowls, tanks, seats, and supply lines are in acceptable working order with no evidence of running or phantom-flush in either fixture. Sink drains clear quickly with no standing water. The shower and tub surround in the primary bathroom shows consistent caulk lines at the tub deck and all corners - no voids, cracks, or mildew are present. The exhaust fan in the primary bath runs when switched on and moves air perceptibly. All surfaces, including mirrors and chrome fixtures, were cleaned during the housekeeping service and show no water spots or soap film.

Issues / Follow-Up: No issues observed. Both bathrooms pass QC.

-

6. BEDROOMS - WALLS, CARPET, CLOSETS, AND HARDWARE

-

Condition Observed: I walked through both bedrooms. Paint on walls and ceilings is even and uninterrupted; corner bead at the ceiling line is straight throughout. Carpet in both rooms is consistent with the rest of the unit - clean, stain-free, and properly stretched with no visible seam gaps or lifting edges at the door thresholds. Closet interiors were checked: shelving brackets are secure, rod hangers are fully seated, and bi-fold door hardware operates without binding or derailing. Window locks engage fully in both bedrooms.

Issues / Follow-Up: No issues observed. Both bedrooms pass QC.

-

7. HVAC - FILTER, SUPPLY VENTS, AND THERMOSTAT

-

Condition Observed: A fresh air filter is installed and seated correctly in the return-air

grille at an appropriate grade for the unit size. I set the thermostat to cooling mode and confirmed the air handler engaged within the expected time delay. Supply vents in each room delivered conditioned airflow without obstruction. The thermostat display is responsive and reading accurately. No evidence of condensation pooling or drain-pan overflow was visible at the air handler access panel.

Issues / Follow-Up: No issues observed. HVAC operation passes QC.

-

8. DEEP CLEAN - OVERALL HOUSEKEEPING REVIEW

-

Condition Observed: Following coordination of the deep clean for this unit, I verified housekeeping results throughout every room. Cabinet faces, appliance exteriors, light fixtures, and window sills are free of dust, grease, and residue. Tiled floor areas are mopped and grout lines appear clean. The baseboards themselves are wiped down - the paint drip documented in Section 2 above is a paint-trade defect rather than a housekeeping deficiency and is logged accordingly. No odors - pet, smoke, or chemical - are detectable in any room of the unit.

Issues / Follow-Up: Housekeeping work is complete and meets the Star Property Management make-ready standard. No housekeeping deficiencies observed.

RECOMMENDATIONS / NEXT STEPS

1. BASEBOARD TRIM TOUCH-UP (Priority - Required Before Unit Release) The dried paint drip on the hallway baseboard trim must be corrected before this unit can advance to a final-pass QC. The lead maintenance technician should lightly sand the affected section, wipe away dust, and apply a spot coat using the same trim paint used during the make-ready to ensure color continuity. This is a minor repair and should require no more than 30 to 60 minutes of labor.

2. RE-INSPECTION AFTER REWORK

Once the baseboard touch-up is finished, a targeted re-inspection of the hallway trim should be conducted and documented. If the corrected area matches the surrounding finish and no further defects are present, the Make-Ready Turn record for Las Vistas Unit 9D should be advanced from QC - Rework Needed to QC - Passed.

3. MAKE-READY TRACKER UPDATE

Upon passing re-inspection, the Make-Ready Turn record should be updated to reflect QC - Passed status so that the leasing team can confirm unit availability and move forward with any prospective applicants currently active in HubSpot for this unit.

4. NOTIFY PROPERTY MANAGER

Lisa Smith should be informed once re-inspection clears so that owner communications and any pending move-in coordination can proceed without unnecessary delay.

5. FILE THIS REPORT IN THE SHARED DRIVE

This Unit Condition Report should be saved to the Las Vistas Unit 9D make-ready folder on the shared document drive and cross-referenced in the Make-Ready Turn record to maintain a complete turnover audit trail for the property.

Inspected and submitted by: Jaime Salinas Maintenance QC Inspector Star Property Management May 19, 2026

END OF REPORT
