

STAR PROPERTY MANAGEMENT

Southwest Texas Residential Portfolio

Make-Ready QC Inspection Report - Las Palmas Unit 8D

Residential Property Management - Southwest Texas Region

-

INSPECTION / ASSESSMENT REPORT

-

Report Title:

Make-Ready Quality Control Inspection - Las Palmas, Unit 8D

Report No.:

SPM-2026-MR-0084

Date Conducted: July 14, 2026

Conducted By:

Subject:

Jaime Salinas, Maintenance Lead - Star Property Management

Unit 8D at Las Palmas, assessed at the conclusion of the make-ready turnover cycle following completion of in-house repairs, vendor carpet work, and full deep cleaning.

Property:

Las Palmas - Star Property Management Portfolio, Southwest Texas

-

I. EXECUTIVE SUMMARY

-

I conducted a full quality control walkthrough of Las Palmas Unit 8D today to confirm that all make-ready work meets Star Property Management standards before the unit is listed as rent-ready. The unit is in substantially good shape overall: drywall repairs, the kitchen faucet replacement, bedroom touch-up painting, the vendor carpet cleaning, and the housekeeping deep clean all came in at an acceptable level. Two minor punch-list items were identified during the walk - a scuffed baseboard in the hallway and a missing outlet cover plate in the bedroom - both of which are straightforward to correct and do not block leasing activity once addressed. Findings have been posted to the #make-ready channel and John Smith has been tagged for follow-up.

-

II. DETAILED FINDINGS

-

2.1 ENTRY / FRONT DOOR AREA --Condition Observed: The front door swings freely, the deadbolt engages cleanly, and the latch hardware shows no looseness or wear from the prior tenancy. The door frame is undamaged and the threshold strip is flush with both the exterior landing and the interior flooring surface.

Issues / Follow-Up: No issues observed. This area is rent-ready as-is.

2.2 HALLWAY

Condition Observed: The hallway corridor is clean and clear of debris. Upper wall surfaces reflect recent paint work and the ceiling shows no water staining or discoloration. The carpet transitioning from the hallway into the main living area is clean following the vendor service completed earlier in this turnover.

Issues / Follow-Up: A visible scuff mark is present on the right-side baseboard trim approximately midway down the hallway. The mark spans roughly four to five inches in length and stands out against the white baseboard finish. The trim itself is not cracked or structurally compromised - this is a cosmetic blemish likely picked up during move-out activity or in the course of repair work traffic through the space. A cleaning pass with an appropriate scuff-removal product or a spot application of matching baseboard paint will resolve it. This item is documented on the punch list and communicated to John Smith.

2.3 LIVING ROOM

Condition Observed: The living room carpet is clean and free of odor following the vendor cleaning service. Wall surfaces throughout the room are in good condition with no visible gouges, heavy scuffing, or unrepaired damage noted. Window blinds are level, fully operational, and intact. I tested the electrical outlets along the perimeter of the room and all are properly covered and functional.

Issues / Follow-Up: No issues observed. The living room meets make-ready standards.

2.4 KITCHEN

Condition Observed: The kitchen faucet replacement has been completed correctly - water flow is steady with adequate pressure, and there is no dripping at the spout or weeping at the base connections. The shutoff valves beneath the sink are in accessible, operable condition. Countertop surfaces, cabinet exteriors, the inside of the oven, and the refrigerator interior all reflect the thorough cleaning completed during the deep clean phase. The sink drain flows without restriction and the tile backsplash grout is clean.

Issues / Follow-Up: No issues observed. The kitchen is in rent-ready condition.

2.5 PRIMARY BEDROOM

Condition Observed: Touch-up paint on the bedroom walls has been applied and blends adequately with the surrounding finish. The carpet in this room was included in the vendor cleaning pass and presents no staining or odor concerns. Closet doors track and slide properly and the closet interior is swept clean.

Issues / Follow-Up: One electrical outlet cover plate is absent on the outlet located on the east wall near the bedroom closet. The outlet box is open and exposed, which is both a cosmetic deficiency and a minor safety concern that must be corrected before the unit is occupied. A standard single-gang cover plate and a single fastener screw are all that is needed to close this item. This has been added to the punch list and flagged to John Smith in #make-ready.

2.6 BATHROOM

Condition Observed: The bathroom received a comprehensive cleaning as part of the deep clean phase. The toilet, vanity sink, and tub/shower enclosure are all clean with no residual soap scum or mildew present. The caulk bead running along the tub surround is intact and shows no visible cracking or separation at the edges. The exhaust fan activates normally and the mirror is secure and clean.

Issues / Follow-Up: No issues observed. The bathroom is in acceptable move-in condition.

2.7 UTILITY / MECHANICAL

Condition Observed: I inspected the HVAC closet and confirmed the air handler is properly seated, the air filter has been replaced with a clean unit, and the condensate drip pan shows no standing water or residue suggesting a drainage concern. The water heater is operational and the connections at the inlet and outlet fittings show no corrosion or mineral buildup. The breaker panel cover is in place, each breaker position is labeled, and no breakers were found in a tripped state.

Issues / Follow-Up: No issues observed. Mechanical systems are in normal working order for this stage of turnover.

2.8 WINDOWS, SCREENS, AND PATIO

Condition Observed: All windows open and latch securely with no binding in the frames. Window screens are in place and undamaged with no tears or missing sections. The sliding patio door moves smoothly along its track and the lock mechanism engages fully. The patio surface is clear of any belongings or debris left from the prior occupancy.

Issues / Follow-Up: No issues observed. Exterior-facing components are in satisfactory condition.

-

III. PUNCH LIST SUMMARY

-

The following two items require resolution before Unit 8D is marked fully rent-ready in Airtable and released to the leasing team for active showings: Item 1 - Hallway Baseboard Scuff

Location: Right-side baseboard trim, approximately midway down the hallway.

Description: Cosmetic scuff mark approximately 4 to 5 inches in length on white baseboard.

Severity: Minor / cosmetic.

Assigned To: John Smith, in-house maintenance. Item 2 - Missing Outlet Cover Plate, Primary Bedroom

Location: East wall outlet adjacent to the bedroom closet.

Description: Single-gang outlet cover plate absent; electrical box is exposed.

Severity: Minor safety item - must be corrected prior to any occupancy or showing.

Assigned To: John Smith, in-house maintenance.

-

IV. RECOMMENDATIONS AND NEXT STEPS

-

1. Address Hallway Baseboard Scuff: John Smith should clean or touch up the hallway baseboard at the earliest opportunity. A scuff-removal sponge or a small amount of matching white baseboard paint will close this item quickly - estimated time is under thirty minutes using supplies already on hand in the maintenance room. 2. Install Bedroom Outlet Cover Plate Immediately: A standard single-gang white cover plate must be installed on the exposed east-wall outlet in the primary bedroom before any applicant is shown the unit. This is a safety item and is not discretionary; the unit should not be presented to prospective tenants through HubSpot or in person until this is confirmed complete. 3. Confirm Punch-List Completion with Photo Documentation: Once both items above are addressed, John Smith should share a brief photo confirmation in the #make-ready channel so the team has a documented close-out on each item. A physical re-spot-check is welcome but photo confirmation is the minimum acceptable verification. 4. Update Airtable Make-Ready Record: After punch-list items are verified closed, the make-ready turn record for Las Palmas Unit 8D should be advanced to full rent-ready status. Brooke Phillips should be notified at that point so leasing agents can activate the unit in HubSpot and begin scheduling showings or processing any applicants who have already expressed interest. 5. File This Report to Shared Drive: This report should be saved in the shared document drive under the Las Palmas / Unit 8D / 2026 Turnover folder, making it accessible to Carlos Mendez, the property manager, and owner relations records as part of the complete documented turnover package.

-

V. CERTIFICATION

-

I certify that the observations and findings recorded in this report reflect conditions as I personally observed them during the walkthrough conducted on July 14, 2026. All noted items are documented accurately and to the best of my knowledge.

Signed: Jaime Salinas Maintenance Lead, Star Property Management July 14, 2026

-

End of Report - SPM-2026-MR-0084
