



Regulators




BMS




TODO FIX: this diode is dissipating a lot
I knew this while designing it and decided
it would usually run off battery power
However, during charging and development

TODO FIX: Add an actual on/off switch while the system is powered off. And a off without needing to unplug



Id: 2/4



Solder jumper configuration
(default "Shared I2C")

	JP5	JP6	JP7	Notes
Shared I2C	1	1	4	Each sensor has INT to MCU
Shared SPI (4 wire)	1	1	2	LIS2 INT configd as missing MISO
I2C Sensor Hub	3	3	3	LIS2 INT handled by LSM6
SPI Sensor Hub	3	3	3	LIS2 handled by LSM6 VIA I2C!

D. Powell

Sheet: /Sensors/
File: sensors.kicad_sch


Title: FR4 lwLIDAR Board

Size: A4 Date: 2025-10-27

KiCad E.D.A. 9.0.9

Rev: A

Id: 3/4



D. Powell

Sheet: /Interfaces/
File: interfaces.kicad_sch

Title: FR4 lwLIDAR Board

Size: A4 Date: 2025-10-27

KiCad E.D.A. 9.0.9

Rev: A

Id: 4/4