

1. Document

1.1 Service log for feedwater pump FP-200, January to March 2026.

2. Seal replacement

2.1 The mechanical seal on FP-200 was replaced on 14 February 2026 after the unit was depressurised.

3. Next service

3.1 The next full service falls due at 2,000 operating hours from the February visit.