version 007 01/01/2021 editor P CAMPBEL

version 006 31/12/2020 editor P CAMPBELL

version 005 14/12/2020 editor Darragh Broadbent
- changed pull up resistor value between IZC multiplexer and slave devices to 3K from 10I

- resolved clearance issue

version 004 12/5/202

version out - removed piezo buzzer - used transistor/P-ch moset for triggering sensirion power - used transistor/P-ch moset for triggering sensirion power

