

Факторы из чисел в выражении ветвей принимаю

$$U_{12} = L_1 R_1 = 0.67 - 1.06 \cdot 4 = 2.68 - 4.25$$

$$U_{23} = X_{12} L_1 = 1.885 \cdot (0.67 - 1.06) = 2.71 - 2.6$$

$$U_{04} = X_{12} L_1 = 7.67 - 7.26 \cdot (0.67 - 1.06) = 7.96 - 4.532$$

$$U_{45} = L_2 R_2 = 0.67 - 0.29 \cdot 16 = 10.23 - 4.71$$

$$U_{56} = X_{12} L_1 = 34.558 \cdot (0.67 - 0.29) = 10.18 + 2.23 \cdot 17$$

$$U_{67} = X_{12} L_1 = 90.946 \cdot (0.67 - 0.29) = 26.29 - 60.92$$

$$U_{48} = L_2 R_2 = 1.34 - 0.77 \cdot 17 = 22.77 - 13.06$$

$$U_{89} = X_{12} L_1 = 21.991 \cdot (1.34 - 0.77) = 16.89 - 29.46$$

$$U_{20} = X_{12} L_1 = 7.0 \cdot (1.34 - 0.77) = -0.470$$