

Pump P201 Failure Report

Failure Report

Unexpected shutdown due to worn mechanical seal.

Corrective Action: Replace seal and inspect bearings.