

Pump P201 Inspection Report

Inspection Report

Minor seal wear detected.

Slight vibration increase.

Pressure normal.

Recommendation: Replace seal.