

Pump P201 Root Cause Analysis

Root Cause Analysis

Repeated seal failures caused by delayed maintenance.

Recommendation: Predictive maintenance using vibration monitoring.