



Graphing a Statistical Process Control Chart in Excel


1) Enter actual data in Excel columns



2) Add columns for Upper Control Limit, Lower Control Limit and Mean values – these should be the same for all periods



3) Create a chart by highlighting all data, clicking "Insert" and choosing the line graph option



4) When the chart is generated, you can modify the styles, axis labels, etc. as desired

