Pinout MESA 7i92

P2	X Dir	Y' Dir	Y" Dir	Z Dir			X limit	Y limit	Z limit	Y" limit	Alarm	EStop	Probe
	100	102	104	106	IO8	109	IO10	IO11	IO12	IO13	1014	IO15	IO16
DB25	1	2	3	4	5	6	7	8	9	10	11	12	13
HDR26	1	3	5	7	9	11	13	15	17	19	21	23	25
HDR26	2	4	6	8	10	12	14	16	18	20	22	24	26
DB25	14	15	16	17	18	19	20	21	22	23	24	25	
	IO1	103	105	107									
	X Stp	Y' Stp	Y" Stp	Z Stp	GND	GND	GND	GND	+5V	+5V	+5V	+5V	+5V
	TXData0	TXData1	TXData2	TXData3	(Quad A)	(Quad B)	(Quad Idx)	(Run)	(Stop)	(Pause)	Spindle Ena	Spindle Dir	Spindle PWM
	IO17	IO19	IO21	1023	IO25	IO26	1027	IO28	IO29	IO30	IO31	IO32	IO33
P1	1	3	5	7	9	11	13	15	17	19	21	23	25
HDR26	2	4	6	8	10	12	14	16	18	20	22	24	26
TIDITEO		-	0	U	10	12	17	10	10	20	22	2-7	20
	IO18	IO20	IO22	1024									
	RXData0	RXData1	RXData2	RXData3	GND	GND	GND	GND	+5V	+5V	+5V	+5V	+5V