

CHAPTER 14 · SPINNING TOP



Step 1



CH2 2 pcs.




PU5 X 7 1 pc.



PU5 X 13 1 pc.

Step 2




G20 Plus
2 pcs.




SH60 2 pcs.

Step 3



G60 2 pcs.

Step 4




CT2 2 pcs.




G20 Plus
1 pc.

Step 5



G60 1 pc.



Motor with
battery Box 1 pc.