

TRINIDAD AND TOBAGO FIRE SERVICE

FIRE REPORT FORM

Commercial Fire
White watch
Tunapuna Fire Station

No. 281

Date Call Received 03/12/2022

Wind: (Strong) (Average) (None)

Time Call Received 1700 Hours

Owner's Name Ricardo Nanan

How Call Received Wireless from Fire Control

Wendy Hosein (Duty Manager)

Address Given Regency Star Hotel

Distance of nearest Hydrant to Fire

30 m

Actual Address of Fire Regency Star Hotel

Cause of Fire

118 BWIA BLVD Piarco

Accidental

Ignition source - Electrical

Time Appliance Left Station 1701 Hours

Was water supply sufficient? Yes ☒ No ☐

Approx. Distance to Fire 8.4 Km

L.P.M. Available 4 x 1000 & 1 x 350

L.P.M. Required Nil

Type of Property

Involved was a three storey structure of A class construction, size approximately 80 m x 40 m registered and used as a Hotel with 158 varying rooms. Same was constructed of steel beams with concrete blocks and mortar. The flooring was concrete screed with clay tiles and the ceiling was gypsum with lightning fixtures and air conditioning ducting running throughout as there was a central air conditioning system. There were large steel framed windows and the internal walls were made of gypsum in certain areas. There was an addressable central fire alarm system with smoke detectors in every room and pull stations and fire extinguishers in relevant places and closest to the exits in all rooms required.

How was Fire Extinguished

The fire was contained to the Conference room of the hotel and extinguished before the arrival of the appliance and crew by #4967 Firefighter Daniel using a dry chemical extinguisher, which was applied directly to the point of origin located on the western side of the room in the air conditioning ducting where the capacitor was situated.

Description of Damage

There were visible signs of fire and smoke damage in the air conditioning ducting and the ducting vent cover. There was also the dry chemical extinguishing medium around the ducting and on the floor space directly below.

Appliances Attending:	Officers Attending:	F.S.S. /O.s Attending:
#654 water Tanker		
#671 Utility		

Number of Men Attending:

3132 Firefighter John, 3184 Firefighter Mills, 3427 Firefighter Jones, 4609 Firefighter Francois, 5001 Firefighter Howard

<i>Professionals</i>	<i>Auxiliary</i>
5	-

List of casualties (Including the members of the service) with brief description of injuries and by whom treated.

1. _____	2. _____
3. _____	4. _____
5. _____	6. _____

Date _____ Signature _____ Rank _____

Value of Building \$ 15,000,000 Value of Stock \$ 5,000,000

Damage to Building \$ 10,000 Damage to Stock \$ Nil

Building and Stock Insured as follows:

Not ascertained

Officer’s Observations

On arrival the duty manager Ms. Wendy Hosein, who carried the crew to the main conference room while explaining that the fire was already extinguished by #4967 Firefighter Daniel. There were visible burnt areas in the A/C ducting and vent cover and a white powder and an expelled extinguisher resting on the floor below.

ADDITIONAL INFORMATION

Ms Hosein stated that persons were in the conference room at the time when smoke was seen emanating from the a/c ducting and firefighter Daniel grabbed the fire extinguisher from the south western wall and extinguished the fire. The maintenance person came and inspected the area and deducted it was the capacitor that overheated and exploded. There was no other ignition sources within the area of origin and the only ignition source closes to the point of origin was the electrical lines and by eye witness accounts stating smoke was seen emanating from the a/c ducting. The duty manager and staff were all advised to switch off the main breaker attached to the air conditioning unit and to have a qualified electrician check the system to have the necessary repairs done before turning it back on.