(ME110)

MECHANICAL ENGG. WORKSHOP

> A Report on: Sheet Metal Working and Soldering

> > NAME: M. MAHEETH REDDY

RULLNO : 1801CS31

Objective:

To prepare a Rectangular Box (open on both sides)

[ Dimensions: 100mm x 50mm x 50mm]

Two caps [with dimensions 50mm x 50mm x 20mm]

Took Required:

Marking Tools / Measuring Tools:

steel rulers, try square, punches, bevel protractor, scriber, divider, trammel points

Cutting Tools:

Snips, Chisels. Shearing Machines etc.

Striking Tools:

Hammer, mallet etc.


Golding Tools:

Soldering torch, Soldering wire, Soldering flux

Holding Tools:

Anvil, Pliers etc.

## DIAGRAM:-



## PROCESSES INVOLVED:

1) Marking - In this process, scribber is used to matek the boundaries of the piece of sheet to be cut and to mark its edges

(P.T.O)

- 2) Shearing In this process, cutter is used to cut the piece of sheet required to make the boxes.
- 3 Bending For this, took like mallet are used to bend the marked edges of the sheet
- 4) Soldering Joining In this process, different parts of the bent sheet are joined using soldering torch and soldering wire.

## PROCEDURE:

- (A) Rectangular Box:
- 1) Using scribbur, mark a sectargle of dimensions 25cm × 10.5cm on the metal shut.
- 2) Cut the overtangle using a cuther.
- 3 with a spacing of 5cm, mark edges of each face of seclargular box, and kend them using a mallet; by repeated hitling for 4-times
- 4 Follow above steps 1 for making 2 caps. cut a rectargle of dimensions 18cm x9cm.

- 5 Later, divide it into 2 sheets of dimensions 90mx9cm
- 6 Mark edges on the sheets so that we get cape of size dimensions 50mm x 50mm x 20cm
- After making caps, solder them box the so that its faces one tightly held. For soldering wed soldering touch, soldering were, there.
- (8) Let it cool for few minutes.

## PRECAUTIONS-

- 1 Always wear gloves while working.
- 2) Never run hands on cut edge.
- 3 Never touch the soldering torch while it is on.
- 4 Always place the torch in its stand when not in use.
- 5 Take Care that the wire of the forch doesn't touch the flame while in use.