
a
b
error budget 0.159 mm
left is better in both panels
Initial calibration only
Clock: 2,700 cycles (train-selected)
Clock: 2,400 cycles (matched cost)
P-V trigger: $\tau = 0.05$
Calibration at every stage
within budget
over budget
tie: 0.058 mm
at 2.0 calibrations
0
0.1
0.2
0.3
0.4
Mean pose RMSE (mm)
0
1
2
3
4
5
Calibrations per actuator