



# Deficiency Report

---

## Property Information

### Test Site with Sprinkler Deficiencies

789 Sprinkler Lane

Vancouver

**Inspection Date:**

December 31, 2024

**Earth Wind Fire Services Inc.**

## Fire Protection Services

604-299-1030 | [info@myfirepro.ca](mailto:info@myfirepro.ca)



## Test Site with Sprinkler Deficiencies

789 Sprinkler Lane  
Vancouver, BC

Job #: TEST-SPRINKLER-001

12/31/2024

## INSPECTION SUMMARY

Service Date: December 31, 2024 | Job #: TEST-SPRINKLER-001 | Technician: Test Technician

### 2 DEFICIENCIES IDENTIFIED

2 Major

*Please review the enclosed deficiency report for full details and corrective action recommendations.*



## Test Site with Sprinkler Deficiencies

789 Sprinkler Lane  
Vancouver, BC

Job #: TEST-SPRINKLER-001

12/31/2024

## Executive Summary

### Deficiency Summary by Severity

| Severity | Count | Status   |
|----------|-------|----------|
| Critical | 0     | None     |
| Major    | 2     | 2 Issues |
| Minor    | 0     | None     |
| Total    | 2     | 2 Issues |

### Deficiency Summary by System

- Other/Uncategorized: 2 deficiencies

### Overall Status:

Major deficiencies should be addressed promptly to maintain compliance.



December 31, 2024

TEST SITE WITH SPRINKLER DEFICIENCIES

TEST CUSTOMER

**ATTENTION: JOHN MANAGER**

EMAIL: manager@test.com

---

**RE: Fire Protection Inspection — Deficiencies Identified**

Test Site with Sprinkler Deficiencies — 789 Sprinkler Lane

Job #TEST-SPRINKLER-001 | Service Date: December 31, 2024

Dear John Manager,

On December 31, 2024, our certified technician, Test Technician, conducted the annual fire protection inspection at Test Site with Sprinkler Deficiencies, located at 789 Sprinkler Lane, in accordance with CAN/ULC S536:2019 and applicable BC Fire Code requirements.

During our inspection, 2 deficiencies were identified that require corrective action. The full details, corrective action recommendations, and associated costs are outlined in the enclosed Deficiency Report.

**2 Major**

To authorize the corrective work, please sign and return the enclosed authorization form. This quotation is valid for 30 days from the date of this letter. Verbal authorization is not accepted — a signed copy must be returned before work will be scheduled.

If you have any questions or require additional information, please do not hesitate to contact our office.

Sincerely,

**Earth Wind Fire Services Inc.**

*Test Technician*

*Fire Safety Inspector*

604-299-1030

[tech@test.com](mailto:tech@test.com)

This letter is intended solely for the use of the addressee. Earth Wind & Fire Protection Services accepts no liability for any loss or damage arising from reliance on this document by any other party. All prices are in Canadian dollars and subject to applicable taxes.



## Test Site with Sprinkler Deficiencies

789 Sprinkler Lane  
Vancouver, BC

Job #: TEST-SPRINKLER-001

12/31/2024

## Sprinkler Deficiencies

| # | Location & Description     | System / Device | Cost     |
|---|----------------------------|-----------------|----------|
| 1 | Office 101. Needs repair   | Sprinkler Head  | \$150.00 |
| 2 | Exterior. Requires testing | FDC             | \$300.00 |

Subtotal: \$450.00

GST + PST (12%): \$54.00

**Total: \$504.00**

### Terms & Conditions

- The proposed quotation is valid for 30 days from the date of receipt of this report. Cancellation after approval of materials will incur a 25% restocking fee.
- Scope of work is based on information in this report. Additional costs for permits, engineering, drawings, aerial lift, sub-trades, rentals, accommodations, and subcontractors will be charged separately. Drywall, fire-stopping, painting, and pipe insulation are excluded.
- GST and PST apply to materials only; GST applies to labour. Taxes are not included in quoted prices.
- All prices are based on regular business hours (8:00 AM – 4:30 PM). An environmental disposal fee of \$7.00/battery applies to all batteries removed. Travel time is included if the majority of repairs are approved simultaneously.
- Prices are based on a single mobilization. Additional trips due to access issues may be charged extra. No travel surcharge for return trips caused by stocking issues.
- A vehicle service charge of \$88.00 will be applied.





## Test Site with Sprinkler Deficiencies

789 Sprinkler Lane  
Vancouver, BC

**Job #: TEST-SPRINKLER-001**

12/31/2024

### AUTHORIZATION TO PROCEED — CORRECTIVE WORK

By signing below, you authorize Earth Wind Fire Services Inc. to proceed with the corrective work detailed in this report at the quoted prices. This quotation is valid until January 30, 2025. Verbal authorization is not accepted. A signed copy must be returned before work will be scheduled.

\_\_\_\_\_  
Authorized Signature

\_\_\_\_\_  
Date

\_\_\_\_\_  
Printed Name and Title

\_\_\_\_\_  
Purchase Order / Reference #



## Test Site with Sprinkler Deficiencies

789 Sprinkler Lane  
Vancouver, BC

Job #: TEST-SPRINKLER-001

12/31/2024

### INSPECTION, TESTING, AND MAINTENANCE OF FIRE ALARM SYSTEMS

CAN/ULC-S536:2019 — Inspection and Testing of Fire Alarm Systems

| Inspection Item                                                                                                                                | Yes                      | No                       |
|------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|--------------------------|
| The entire fire alarm system has been inspected and tested in accordance with CAN/ULC-S536:2019, Inspection and Testing of Fire Alarm Systems. | <input type="checkbox"/> | <input type="checkbox"/> |
| The fire alarm system is fully functional.                                                                                                     | <input type="checkbox"/> | <input type="checkbox"/> |
| During the inspection and test, were any Deficiencies Identified? (See attached deficiency report, if applicable.)                             | <input type="checkbox"/> | <input type="checkbox"/> |
| During the inspection and test, were any Recommendations Identified?                                                                           | <input type="checkbox"/> | <input type="checkbox"/> |

The information in this report, which comprises 10 pages, affirms that the equipment listed here-in was tested and inspected in conformance with ULC 536:2019 (2024); Standard for Inspection and Testing of Fire Alarm Systems, applicable codes, bylaws, Standards, and the manufacturer's requirements by a qualified technician. The equipment was left in an operational condition except as noted above.

| Supervising / Primary Technician Name | Certification Number / Seal                               | Date       | Signature                     |
|---------------------------------------|-----------------------------------------------------------|------------|-------------------------------|
| Test Technician                       | <div>FIRE PROTECTION<br/>ASTTBC<br/>TEST TECHNICIAN</div> | 2024-12-31 | Earth Wind Fire Services Inc. |

|                          |                               |        |              |
|--------------------------|-------------------------------|--------|--------------|
| Company Conducting Test: | Earth Wind Fire Services Inc. | Phone: | 604-299-1030 |
|--------------------------|-------------------------------|--------|--------------|





















