







DISTRIBUTION DIAGRAM OF SHEAR STRESS IN BEAM SECTIONS

Section	Shear stress diagram	$T_{\max}$
		$\tau_{\max} = \frac{3Q}{2bh} = \frac{3}{2} \frac{Q}{A}$
		$\tau_{\max} = \frac{9}{4} \frac{Q}{bh} = \frac{9}{8} \frac{Q}{A}$
		$\tau_{\max} = \frac{4}{3} \frac{Q}{\pi r^2} = \frac{4}{3} \frac{Q}{A}$
		$\tau_{\max} = \frac{4}{3} \frac{Q}{\pi r r^1} = \frac{4}{3} \frac{Q}{A}$
		$\tau_{\max} = \frac{3}{2} \frac{(BH^2 - bh^2)(BH - bh)}{2(BH^3 - bh^3)(B - b)} \frac{Q}{A}$
		$\tau_{\max} = \frac{4(r_2^2 + r_2 r_1 + r_1^2)}{3(r_2^2 + r_1^2)} \frac{Q}{A}$

YICK HOE