In the lastest platform, such as MSM8952,MSM8976,MSM8996, we support QC3.0 from SW.

If don't want to use QC3.0, can disable it through below method,

For example 8996,

=========

remove or comment out the following service from "/device/qcom/msm8996/init.target.rc" and rebuild:

service hvdcp_opti /system/bin/hvdcp_opti class main user root group root