

Detailed Diagnostic Report

Detailed Diagnostic Report (DDR)

1. Property Issue Summary

Multiple dampness and seepage issues have been identified across the property, particularly in Hall, Bedroom, Bathroom, and External wall areas. Both inspection and thermal reports confirm moisture intrusion.

2. Area-wise Observations

Hall

- Dampness observed at skirting level
- Paint deterioration and moisture marks present
- Thermal readings indicate cold spots (~2023°C)
- Image: Inspection/Thermal reference (if available)

Bedroom

- Dampness and wall damage observed
- Thermal variation (~2227°C) confirms seepage zones
- Image: Inspection/Thermal reference (if available)

Bathroom

- Gaps in tile joints and possible plumbing issues
- High probability of water ingress due to poor sealing
- Image: Inspection reference (if available)

External Wall

- Cracks observed on wall surfaces
- Risk of water penetration from exterior
- Image: Inspection reference (if available)

3. Probable Root Cause

- Capillary action due to tile joint gaps
- External wall cracks allowing water ingress
- Inadequate waterproofing
- Possible plumbing leakage

4. Severity Assessment

Moderate to High

Reason:

- Multiple impacted areas
- Confirmed by both inspection and thermal analysis

- Potential structural damage if untreated

5. Recommended Actions

- Seal tile joints using waterproof grout
- Apply external waterproof coating
- Repair cracks in walls
- Inspect and fix plumbing systems
- Improve drainage and slope

6. Additional Notes

Thermal analysis confirms hidden moisture zones.

No major conflict observed between inspection and thermal findings.

7. Missing Information

- Roof condition: Not Available
- Structural audit report: Not Available