1		2	3	4	5	6
Project Curren	t: L nt Revision: R	OM0250TG ROM0E0				
DM025	50TG Revision	n History:				
Date 12/30/2020	Revision BG0250TG-> R0M0E0	Reason for Change	Changes Implemented 1) Added protection diodes to MIPI lines 2) Changed FFC with Molex 505278 series 3) Sandarized 41. stackup			
		1) ESD protection 2) FFC connector stronger mechanics 3) Outdated stackup	Changed FFC with Molex 505278 series Standarized 4L stackup			
					Title DM0250TG	Luxonis Holding 1925 Harmony Park Drive n:ROMOEO Cannot open file C:Users BrianLuxo
					Size: Tabloid Number: D0000999 Revisic Date: 3.01.2021 Time: 21:34:44 Sheet 1 Drawn by: David Malovrh	n:ROM0E0 Westminster, CO 80234 Cannot open file C:\Users\BrianLuxor of 3 United States



