

Project: BK1096 Current Revision: R1M0E1 BK1096 Revision History: Date 07/31/2020 Revision Reason for Change **Changes Implemented** R0M0E0 --> R1M0E1 1) Slow plug issue with USB type-C 1. Added 1uF capacitor to VBUS_DET updated PCB and fabrication files 04/21/2021 Luxonis Holding 1925 Harmony Park Drive Westminster, CO 80234 Title **BK1096** Cannot open file C:\Users\BrianLuxonis\ Size: Tabloid Number:D000 Revision:R1M0E1 Time: 13:55:06 Sheet 2 of 6







