Project: DM10981 Current Revision: R1M0E1 DM1098LUX-D-LITE

DM1098LUX-D-LITE Revision History:

1	Date	Revision	Reason for Change	Changes Implemented
	04/22/2021	Initial release		
İ	06/07/2021	R0M0E0 -> R1M1E1	1. USB SS port direction control issue	1. Switched CC1 CC2 on logic control chip for USB3 SS

Title DM1098LUX-D-LITE Cannot open file C:\Users\BrianLuxonis\















