1 2 3 4 5

Project: DM1095 Current Revision: R0M0E0

DM1095 Revision History:

Date	Revision	Reason for Change	Changes Implemented
04/22/2021	Initial release		
06/07/2021	R0M0E0 -> R1M0E1	1. USB SS port direction control issue	1. Switched CC1 CC2 on logic control chip for USB3 SS
	DM1098LUX-D-LITE_R1M0E1 -> DM1095_R0M0E0	1. Update the project naming convention to follow new scheme	1. Updated the project naming convention exported new fabrication documentation
10/09/2021	DM1095_R0M0E0 -> DM1095_R0M0E1		Updated the specifications and power sequence for IMX214 and OV7251 cameras. Removed the 1.5V power supply for the OV7251 camera from the Production variant Generated new assembly documentation

Title DM1095

Size: Tabloid Number:DXXXX Revision:ROMOED Westminster, CO 80234

Date: 19/10/2021 Time: 12:33-89 Sheet of 9 United States

Cannot open file Cann

1 2 3 4 5 6















