BW109	97 Revision Hist	fory:		
Date	Revision	Reason for Change	Changes Implemented	
11/29/2019	RIMIE2 → R2M2E3	1) Updating board to be aligned with Gen2 1099 boards, with SPI and stD 2) Header jumpers are unnecessiry and expensive, and can be repaleed with a simpler solution 3) Existing design was not standardized on LuxonisMaster library format 4) Series input power resistor is a sense resistor, but should be 0 ohm 5) The OV9282 LDOs have unnecessary components compared to the most rec baseboards 6) Depopped R26 had no set component value. 7) HDMI connector footprint was found to be slightly crooked 8) PGOOD LED driver did not match other boards 9) DMG1012 FETs were automotive qualified, changed to non-automotive for entry into LuxonisMaster 10) Passive component equivalent part substitions as library was built up		
DM10 9	97 Revision Hist ROMOED -> ROMOEL ROMOEI -> RIMIE2	ory:		
	R1M1E2 -> R2M2E3			































