1 2 3 4 5

Project: DM1095 Current Revision: R0M0E0

## DM1095 Revision History:

| Date       | Revision                                    | Reason for Change  | Changes Implemented   |
|------------|---|--|---|
| 04/22/2021 | Initial release                             |  |   |
| 06/07/2021 | R0M0E0 -> R1M0E1                            | 1. USB SS port direction control issue                       | 1. Switched CC1 CC2 on logic control chip for USB3 SS   |
|            | DM1098LUX-D-LITE_R1M0E1 -><br>DM1095_R0M0E0 | 1. Update the project naming convention to follow new scheme | 1. Updated the project naming convention exported new fabrication documentation   |
| 10/09/2021 | DM1095_R0M0E0 -> DM1095_R0M0E1              |  | Updated the specifications and power sequence for IMX214 and OV7251 cameras.     Removed the 1.5V power supply for the OV7251 camera from the Production variant     Generated new assembly documentation |

Title DM1095

Size: Tibloid Number: DXXXX Revision:ROMOED Westimister, CO 80234

Date: 20/10/0212 Time: 10/07/00 Sheet of 9 United States

Cannot open file Calloning Colleges (Brain Luxonis) Colle

1 2 3 4 5 6















