1 2 5 6

Project: DM0249
Current Revision: R0M0E0

DM0249 Revision History:

Date	Revision	Reason for Change	Changes Implemented
12/4/2019	ROMOEO -> R1M1E1	1) Slot for camera did not get correctly generated in gerbers 2) Library and components not common w Luronis/Master 3) BW1098FFC production will standardize on bottom-side contact connector, so for "face down" BG0249 orientation, we need a same-side contact flex.	1) Updated camera footprint, removed duplicace board cutout, fixed physical board shape in Altium, and removed unnecessoral parts from project. 2) Updated all components to the new Laxonis Master library format in order to standardae layer usage, supply chain, and dark. Some caps and resistons changed footprints and MFRs to align with Lusonis Master, but no component values were changed. Only exception is a change to the SwReg inductor to DFEZSOL 2P. RIOM-P2, which has some inductance, higher current rating, and is being used on other Luxonis boards in this application. 3) Changed files from oppositie-side Wurth 687726152002 to same-side Molex 0151660281. Molex FFC is about \$0.75 cheaper, too.
12/28/2020	RIMIE1 -> R0M0E0	ESD protection Fire Connector stronger mechanics Outdated stackup	1) Added protection diodes to MIPI lines 2) Changed FFC with Molex 505278 series 3) Standarized 4L stackup

	Title DM0249				Luxonis Holding 1925 Harmony Park Drive		
	Size:	Tabloid	Number: D000103	Revision:R0M0E0	Westminster, CO 80234	Cannot open file C:\Users\BrianLuxonis\	
I	Date:	4.01.2021	Time: 15:23:24	Sheet1 of 3	United States	11-11	

1 2 3 4 5



