

Industrial Inspection Report

Inspection Date: 28 August 2026

Facility: Manufacturing Plant A

Inspection Type: Routine Safety and Equipment Inspection

1. Executive Summary

A routine inspection was conducted to assess equipment condition, workplace safety, and compliance with operating procedures. Several maintenance and safety issues were identified and require corrective action.

2. Equipment Condition

The main production machine was operational but showed excessive vibration near the drive assembly. One protective guard was loose and should be secured before continued heavy operation. Preventive maintenance records were also incomplete for the previous service cycle.

3. Safety Violations

Three safety issues were observed: an emergency exit was partially obstructed by stored material, two electrical panels were missing updated warning labels, and one worker was observed without the required eye protection in the machining area.

4. Electrical Observations

Electrical panels were generally in serviceable condition. Two panels require updated hazard labels. No exposed live conductors were observed during the inspection.

5. Corrective Actions

The facility should clear the emergency exit immediately, replace the missing electrical warning labels, enforce mandatory eye protection in the machining area, inspect and secure the loose machine guard, investigate excessive vibration, and update preventive maintenance records.

6. Inspector Recommendation

A follow-up inspection should be completed within 14 days to verify that the identified corrective actions have been implemented. High-priority safety issues should be addressed immediately.

Inspection Findings Summary

Finding	Priority	Recommended Action
Obstructed emergency exit	High	Clear immediately
Missing electrical warning labels	Medium	Replace labels
Missing eye protection	High	Enforce PPE requirement
Loose machine guard	High	Secure and inspect
Excessive machine vibration	Medium	Investigate and service