

# INSPECTAI

Industrial Inspection Report

## Inspection Details

|                  |            |
|------------------|------------|
| Inspection       | dfyef      |
| Location         | Patna      |
| Inspector        | fgrh       |
| Inspection Date  | 2026-09-16 |
| Status           | completed  |
| Risk Level       | HIGH       |
| Compliance Score | 80%        |

## Inspection Summary

The inspection was assessed with an overall risk level of **HIGH** and a compliance score of **80%**. A total of **3** finding(s) were identified.

## Inspection Findings

### 1. Missing eye protection

|          |                                         |
|----------|-----------------------------------------|
| Severity | HIGH                                    |
| Category | Safety                                  |
| Status   | OPEN                                    |
| Page     | 2                                       |
| Source   | Construction Site Safety Inspection.pdf |

**Description:** One worker was observed without required eye protection, posing a risk to their safety.

**Recommendation:** Enforce mandatory eye protection

### 2. Loose scaffold toe-board

|          |                                         |
|----------|-----------------------------------------|
| Severity | HIGH                                    |
| Category | Structural                              |
| Status   | OPEN                                    |
| Page     | 2                                       |
| Source   | Construction Site Safety Inspection.pdf |

**Description:** One toe-board section on the scaffolding requires refastening, posing a risk to workers.

**Recommendation:** Secure and inspect the scaffolding

3. Cable trip hazard

|          |                                         |
|----------|-----------------------------------------|
| Severity | MEDIUM                                  |
| Category | Safety                                  |
| Status   | OPEN                                    |
| Page     | 2                                       |
| Source   | Construction Site Safety Inspection.pdf |

**Description:** A temporary cable was routed across an access path, creating a potential trip hazard.

**Recommendation:** Reroute or protect the temporary cable

Corrective Actions

| Action | Assigned To | Priority | Due Date   | Status      |
|--------|-------------|----------|------------|-------------|
| twqt3w | yey         | HIGH     | 2026-09-26 | IN PROGRESS |