

INSPECTAI

Industrial Inspection Report

Inspection Details

Inspection	Risk Inspection
Location	Hyderabad
Inspector	Abhishek
Inspection Date	2026-09-06
Status	completed
Risk Level	HIGH
Compliance Score	75%

Inspection Summary

The inspection was assessed with an overall risk level of **HIGH** and a compliance score of **75%**. A total of **5** finding(s) were identified.

Inspection Findings

1. Obstructed emergency exit

Severity	HIGH
Category	Safety
Status	OPEN
Page	1
Source	filename.pdf

Description: An emergency exit was partially obstructed by stored material, posing a significant safety risk.

Recommendation: Clear the emergency exit immediately

2. Missing electrical warning labels

Severity	MEDIUM
Category	Electrical
Status	OPEN
Page	1
Source	filename.pdf

Description: Two electrical panels were missing updated warning labels, which could lead to electrical shock.

Recommendation: Replace the missing electrical warning labels

3. Missing eye protection

Severity	HIGH
Category	Safety
Status	OPEN
Page	1
Source	filename.pdf

Description: One worker was observed without the required eye protection in the machining area, posing a safety risk.

Recommendation: Enforce the mandatory eye protection requirement

4. Loose machine guard

Severity	MEDIUM
Category	Machinery
Status	OPEN
Page	1
Source	filename.pdf

Description: One protective guard was loose and should be secured before continued heavy operation.

Recommendation: Secure and inspect the loose machine guard

5. Excessive machine vibration

Severity	MEDIUM
Category	Machinery
Status	IN PROGRESS
Page	1
Source	filename.pdf

Description: The main production machine was operational but showed excessive vibration near the drive assembly.

Recommendation: Investigate and service the machine

Corrective Actions

No corrective actions have been created.