

# Fire Safety Inspection

**Inspection Date:** 13 September 2026  
**Facility:** Office and Warehouse Complex  
**Inspection Type:** Routine Fire Safety Inspection

## 1. Executive Summary

A routine fire safety inspection was conducted to review emergency exits, fire extinguishers, alarm access, evacuation routes, and fire safety signage. The facility was generally satisfactory, with a small number of corrective actions required.

## 2. Fire Equipment Condition

Fire extinguishers inspected were mounted and accessible. One extinguisher inspection tag requires updating. Fire alarm access was unobstructed during the inspection.

## 3. Safety Violations

A storage box was found partially obstructing an emergency exit route. One fire-safety sign near the warehouse entrance was faded.

## 4. Emergency Access Observations

Emergency routes were generally clear. The affected exit should be cleared immediately and the area should be monitored to prevent recurring obstruction.

## 5. Corrective Actions

Remove the obstruction, update the extinguisher inspection tag, replace the faded fire-safety sign, and reinforce housekeeping requirements around emergency routes.

## 6. Inspector Recommendation

Conduct a follow-up verification within 14 days and include emergency-route checks in routine daily housekeeping inspections.

## Inspection Findings Summary

| Finding                   | Priority | Recommended Action    |
|---------------------------|----------|-----------------------|
| Partially blocked exit    | High     | Clear immediately     |
| Outdated extinguisher tag | Medium   | Update inspection tag |
| Faded fire sign           | Low      | Replace signage       |