
Stepper motor



```
Code:
void main(){
    TrisB=0x00;
    portb=1;
    do{
        Portb=0b00000011;
    delay_ms(500);
    portb=0b00000110;
    delay_ms(500);
    portb=0b00001100;
    delay_ms(500);
    portb=0b00011000;
    delay_ms(500);
    portb=0b00011000;
    delay_ms(500);
}
while(1);
```