
## Sectors (rotor positions) and phase orientation of a 2 phase machine



Sectors (rotor positions) and phase orientation of am asynchronous 6 phase machine

